Bulletin #: 1814 Part ID: 9128

G2 Panamera and E3 Cayenne Coaxial Cable Ordering Concept

Vehicles Affected

Model	Model Year	Model Type	VIN Range	Vehicle Specific Equipment
Panamera G2	2017-on	971	n/a	n/a
Cayenne E3	2019-on	9YA	n/a	n/a

Revision History

Revision	Release Date	Changes	
0	November 16, 2018	Initial Release	

Condition (Customer complaints/workshop findings)

The customer may have various complaints about system malfunctions related to coaxial cable connection issues. (Coaxial cables carry various electronic signals, including antenna amplifier and video.) Often, these malfunctions are accompanied by fault codes that implicate the cable itself. The workshop determines to repair the cable.



Bulletin #: 1814 Part ID: 9128 9

Service Information (Instructions to technician)

Repairing the coaxial cable will require parts that are particular to the needed application. A single complete coaxial cable is no longer available for order. Therefore, follow this basic concept to order the correct parts:

Ordering Coaxial Cable

- 1. Determine the specific length of base coaxial cable needed. Note: 300 mm is approximately 12 inches. (See figure 1 for a G2 Panamera example.)
 - a. For E3 Cayenne, see PET 911-020 item 2
 - b. For G2 Panamera, see PET 911-020 item 3



Figure 1



Bulletin #: 1814

Part ID: 9128

9

Service Information (Instructions to technician) (cont'd)

- $\ensuremath{\text{2.Select}}$ both specific coaxial cable ends. See figures 2 and 3.
 - a. See PET 911-020 item 1. (Figure 2.)



Figure 2



Bulletin #: 1814 Part ID: 9128 9

Service Information (Instructions to technician) (cont'd)

- 2. Select both specific coaxial cable ends. See figures 2 and 3. (cont'd) Example of a cable end.
 - b. Each end of the coaxial cable needs to be ordered separately.



Figure 3

c. Determine which part to order by looking at the connector in the vehicle. (Figure 4.) This connector number corresponds to the underlined number in PET. (See figure 5.)



Figure 4

AfterSales

November 16, 2018 Page 4 of 6



Bulletin #: 1814 Part ID: 9128

Service Information (Instructions to technician) (cont'd)

- 3. If one end will be at the rear deck lid, consider the matching rear deck lid harness.
 - a. The antenna amplifier harness is available with the deck lid harness and does not need to be ordered separately.
 - b. See PET 902-040 Item 2 & 3.

NISCHE!		IALS STANDARD HARDWARE	NEW AND DROPPED PARTS	ADMINISTRATION	O ON OFF	ORDER FORM	DEPOT ORDER FORM
AF2A79HL153299	MODEL YEAR MG SG ILLUSTRATION	SEARCH	NEW AND DROPPED PARTS	ADMINISTRATION			
Qaal			OHIE H POS	PART NUMBER	DESCRIPTION		REMARK QTY MODEL
			1	971 998 054	Aerial connection line Connector housing 6Q0.035.576.J		1
8			(1)	971 998 057	Aerial connection line Connector housing 6Q0.035.674.F	Connector 6Q0.035.674.I 971.998.057	
		- 	(1)	971 998 058	Aerial connection line Connector housing 6Q0.035.576.C		
			(1)	971 998 068	Aerial connection line Connector housing 4L0.035.576.A		1
			(1)	971 998 076	Aerial connection line Connector housing 6Q0.035.575		1
	and a stand	60	(1)	971 998 102	Aerial connection line Connector housing 4L0.035.576.B		1
	11 0 3 0		(1)	971 998 103	Aerial connection line Connector housing 6Q0.035.576		1
			(1)	971 998 109	Aerial connection line Connector housing 6Q0.035.674.C		1
	12	10	(1)	971 998 110	Aerial connection line Connector housing 6Q0.035.575.A		1
		11	(1)	971 998 122	Aerial connection line Connector housing 4L0.035.576.D		1
MARKE	ET ORDER	EC TC CVDA COD	ITC DS2 AC	CHASSI	s ND F2A79HL153299	PRODUCTION 11.05.2017	SALES TYPE C 97AFF1 F

Figure 5

Repair Tips

- 1. Be sure the repaired cable is routed correctly in the vehicle. Overlay the original cable carefully.
- 2. Do not route the repaired cable in a manner (a) that interferes with other wiring, (b) that pinches the coaxial cable, or (c) that creates tensile or compressive stress.



Bulletin #: 1814 Part ID: 9128 9

Search Items (Tags, keywords, etc that can be used to search for this document)

Cable, Coax

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part humbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche technicians have the safet generation of the safet generation of followed.



November 16, 2018 Page 6 of 6