

# **Preliminary Information**

## PIT5520B Floor Center Console Compartment Sliding Door Latch Broken or Inoperative

<u>Models</u>

Dressel		Model Years:	VIN:		E	Torradiation		
Brand:	Model:		from	to	- Engine:	Transmissions:		
Cadillac	Escalade	2015 - 2019	All	All	All	All		
Involved Region or Country:		North America						
Additional RPO/s:		N/A						
		Some customers may comment that the floor center console sliding compartment door (1) is broken. Upon inspection it may be found that the door will not latch open, or may be locked in the closed position.						
Condition:								
Cause:		This issue is caused when the sliding door - which is intended to be a push-to-open / push-to-close, or "push-push" door – is pulled to close. The push handle on the sliding door may be misunderstood to be used as a pull handle to close the door. When the sliding door is pulled closed it can damage/break the latch (2).						

Correction:

Do NOT replace the floor center console compartment assembly.

Do replace the compartment sliding door latch, GM Part # 23417257 and educate the customer on proper pushpush operation for the sliding door.

The sliding door latch (2) has been made available to repair this condition without having to replace the floor center console compartment assembly.

- Follow SI repair instructions titled "Front Floor Console Cup Holder Door Latch Replacement (Cadillac)", Document ID 4255612 to replace the latch.

- Educate the customer on proper push-push operation for the sliding door to prevent the latch from breaking again.

TIP: If the sliding door is locked in the closed position the inertia lock (3) will need to be reset by depressing the release tab (4) on the underside of the console assembly, as shown below.



#### Parts Information

Description:	Part Number:	Qty:
LATCH ASM-F/FLR CNSL CUP HLDR DR	23417257	1

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description:	Labor Time:
1034660	Front Floor Console Cup Holder Latch Replacement	Use Published Time

### Version History

Version	3
	08/22/2016 Created on.
Modified	9/20/2017- This PI was superseded to add 2017 model year.
	12/17/20185 Updated to add 2018-2019 Model Years.



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.