



SI B51 02 19
Body Equipment

February 2019
Technical Service

POWER WINDOW REVERSES WHEN CLOSING

MODEL

G29 (Z4 Roadster)

Produced from September 1, 2018 thru January 4, 2019

SITUATION

When closing either of the front windows, the windows will anti-trap and reverse when approaching the fully closed position.

CAUSE

Software sensitivity of the front window anti-trap mechanism.

CORRECTION

1. Perform diagnosis with ISTA and work through the corresponding test module if necessary. If no faults are found, proceed to step 2.
2. Program/encode the vehicle using ISTA 4.15.3x (I-Level 18-11-565) or higher.



Note: Parts replacement will not provide a solution to this situation.

PROCEDURE

1. Program/encode the vehicle using ISTA 4.15.3x (I-Level 18-11-565) or higher.

Always connect a BMW-approved battery charger/power supply (SI [B04 23 10](#)) when performing programming.

For information on programming and coding with ISTA, refer to CenterNet / TIS / Technical Documentation / Programming and Diagnostics / Programming Documentation

2. Fully raise the window several times to confirm that the original fault no longer occurs.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	6762041400	Initialization loss, power windows, front	
Labor Operation:		Labor Allowance:	Description:
00 00 006		Refer to AIR/KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults) (Main

			work)
Or:			
00 00 556		Refer to AIR/KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults) (Plus work)
And:			
61 21 528:		Refer to AIR/KSD2	Connect an approved battery charger/power supply (indicated in KSD2 as “Charging battery”)
And:			
61 00 730		Refer to AIR/KSD2	Programming/encoding control unit(s)

Labor operation code 00 00 006 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to AIR/KSD2 for the corresponding flat rate unit (FRU) allowances.

During the same workshop visit, if a vehicle also requires another Technical Campaign or repair that also includes programming and encoding the control units, the programming procedure may only be invoiced one time.

Programming and Encoding - Vehicle Control Units

A. The programming procedure automatically reprograms and encodes all vehicle control modules which do not have the latest software i-level. If one or more control module failures occur “during” this programming procedure:

- Claim this “consequential” control module-related repair work under the defect code listed in this bulletin with the applicable AIR/KSD2 labor operations

Please explain this additional work (The why and what) on the repair order and in the claim comments section.

B. For control module failures that occurred “prior” to performing this programming procedure:

- When “covered” under an applicable limited warranty, claim this control module-related repair work using the applicable defect code and labor operations (including diagnosis) in AIR/KSD2

Other Repairs

Under the terms of the BMW New Vehicle Limited Warranty, if other eligible and covered work is performed as a result of performing the ISTA diagnostics and the related test plans, claim this work with the defect code and labor operations in AIR/KSD2 that apply (including diagnosis with separate punch times, as applicable).

[Copyright ©2019 BMW of North America, Inc.]