

## **Service Bulletin**

File in Section:

Bulletin No.: 18-NA-361

Date: December, 2018

## **TECHNICAL**

**Subject:** Diagnostic Tip for Fuel System Contamination


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	]	
Chevrolet	Silverado	2017	2018				
	Silverado 2500/3500	2019	2019			L5P	
GMC	Sierra	2017	2018			LSP	
	Sierra 2500/3500	2019	2019				

Involved Region or Country	North America					
Condition	5168457  Some technicians may find metal particles in the fuel system during diagnostics.					
	If you encounter such a situation. <b>DO NOT</b> replace the fuel system as described in 16-NA-102.  Please perform the following fuel system flushing procedure prior to performing further diagnostics					
Correction						
	Once the fuel system has been flushed, continue with diagnostics as described in SI.					

## **Fuel System Flushing Procedure**

**Note:** Performing the test may aid in determining the source and section of the fuel system causing the contamination.


1. If removed, re-install the fuel filter.



5167517


- 2. Disconnect the chassis side fuel feed hose (3) from the engine side fuel feed pipe (4).
- Place the end of the chassis side fuel feed hose into a clean container and run the fuel pump to clean any debris left in the fuel lines, approximately 2-3 gallons.
- 4. Install new fuel filter.
- 5. Disconnect the chassis side fuel return hose (2) from the engine side return pipe (1).

**Note:** The white "Tubing" shown in the graphics below depict the route of the clear line, not the length.



6. Install a clear line between the fuel supply hose and the fuel return hose.

7. Run the fuel pump until the fuel runs clear in the line.



5168447

- 8. Connect the fuel supply hose to the engine supply pipe.
- 9. Install a clear line in series at the fuel return hose to the engine return pipe.
- 10. Run the fuel pump until the fuel runs clear in the line.

Reconnect all fuel lines and retest for any codes or symptoms in the vehicle.

## **Parts Information**

No parts are required for this repair.

Bulletin No.: 18-NA-361 December, 2018 Page 3

Version	1
Modified	Released December 10, 2018