

## Service Bulletin

File in Section:

Bulletin No.: 18-NA-332

Date: November, 2018

# **TECHNICAL**

Subject: Malfunction Indicator Lamp (MIL) On, DTC P2097 Set

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to	Engine.	Transmission.
Chevrolet	Volt	2016	2017			Equipped with 1.5L Engine (RPO L3A)	

Involved Region or Country	North America and N.A. Export Regions		
Condition	Some customers may comment on the malfunction indicator lamp (MIL) being on. Technicians may find DTC P2097 set.		
Cause	This condition may be caused by a software anomaly.		
Correction	An updated software calibration has been released to address this condition.		

#### **Service Procedure**

**Important:** Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the *EL-49642* SPS Programming Support Tool (GM Dealer Equipment Item #PSC-550) to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

Refer to Engine Control Module: Programming and Setup in SI.

#### **Parts Information**

No parts are required for this repair.

### **Warranty Information**

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time		
2886078*	Engine Control Module Reprogramming with SPS	0.3 hr		
*This is a unique Labor Operation for Bulletin use only.				

Version	1
Modified	Released November 1, 2018