VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE: Software download problem - "PSCM failed to enter programming session"

REF NO:	ISSUING DEPARTMENT:	CAR MARKET:			
TJ 33552.2.0	Technical Service	United States and Canada			
3 US 7	PARTNER:	ISSUE DATE:	STATUS DATE:		
	2510 Volvo Car USA	2018-08-06	2018-08-08		
FUNC GROUP: 3648	FUNC DESC: Software	Page	1 of 3		

"Right first time in Time"

Attachment

File Name	File Size		
PSCM prog msg.png	0.3248 MB		

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range	
536							2019-2019		0000001-99999999	201746-201846	

CSC Customer Symptom Codes

Code	Description
1Z	Service/repair/Software update failed

VST Operation Number

DTC Diagnostic Trouble Codes

Rows beginning with * are modified Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

Technical Journal 33552.2.0



DESCRIPTION:

When downloading large package software (PDS upgrade, Total Upgrade or Service 2.0), a message may occur stating "PSCM failed to enter programming session" (see attached screenshot).

SERVICE:

If message occurs in VIDA, press and hold the start button for at least 7 seconds, to get the vehicle into usage mode "active" and reattempt the software upgrade.

To avoid the fault, set the vehicle to usage mode "active" before start of download, by pressing and holding the start button for at least 7 seconds.

If the message still occurs download a PSCM Upgrade, part number 32221476. Once the PSCM upgrade completes refresh the software list in VIDA and reattempt the large package software download (PDS upgrade, Total Upgrade or Service 2.0).

PDS - Pre Delivery Service PSCM - Power Steering Control Module VIDA - Vehicle Information and Diagnostics for Aftersales

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3648.

To view TJ attachment continue to next page. This TJ has one attachment.



Technical Journal 33552.2.0

Home XCA	N; 2019A, 154204718	9									Dank	ei Your
Planning	Diagnostics: Softwa	re intermation							Q	=	0 ^D	Ċ
		YV4182X28K2000000 XC40, 2019A, 000000		Customer Nan	NE.		Connection -	++ #29 (P Active	1			
urchase Software	Download Software								C.	Advance	t Tini	Ģ
Downtoood Queue	consist interior				informatio	n (1						
Døder ID	Order Date		Status		-					-	7	05
665910678290785372		Availa	ble .								_	
Selected Parts Part Number	Description	Comments	Size (kB)	Downlos	0	Downloading so	offware					
12 31676057	Service 2.0 upgrade	Commence	191143	50	-	(PSCM)()Falled	to enter programming session					
+ [28 Yo 2 0 spy ave		iaring	*								
1												
							Ok					
					1		1.000 million				-	
					1							
					1							
VIN		YV4162XZ8K2000000 :										
VIN Order reference			C60 004 005									
Order Details VIN Order relatence Central modules to be load Size		YV4162X28K2000000 ASOM, AUD, CCM, CEM 196.7 MB	CSD, DOM, DEN	, Dim. IH								