



Technical Journal

TITLE:

***Gear shift lever inoperative**

REF NO: TJ 32469.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-02-20	STATUS DATE: 2018-03-01
FUNC GROUP: 4323	FUNC DESC: Gear lever, complete	Page 1 of 6	

“Right first time in Time”

Attachment

File Name	File Size
TJI-503582-1_1_1_en-US.pdf	1.4504 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2018		-	201617-201816
235							2017-2018		-	201624-201816
236							2016-2018		-	201644-201816
238							2017-2018		-	201646-201816
246							2017-2018		-	201646-201816
256							2016-2018		-	201505-201816

CSC Customer Symptom Codes

Code	Description
7G	Text window and warning symbol/Yellow symbol and text message
IV	Text window and warning symbol/Text message
MP	Automatic transmission/Possible to change gears, Shift lock does not work



VST Operation Number

VST Operation Number	Description
98677-2	Inspection Selector Lever Assembly
36001-2	Diagnostic trouble codes with VIDA

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
TCM	P086087	Permanent
ECM	U010387	Permanent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

*Updated with additional VST Operation No, Description and Title.

*If the gear shift lever is inoperative and if any DTCs are set individually or together, please follow the advice under "Service".

SERVICE:

Disconnect and reconnect the connector at the GSM, according to attached method. Reset the DTCs and test gear shift lever.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 4323.

To view TJ attachment continue to next page. This TJ has one attachment.



Volvo Car Customer Service

TJ Instruction VCC-503582-1


Title	Selector Lever Assembly	Page	1 (4)
Action	Inspection	Operation number:	98677-2

Issue	Date	Reason
1	2017-04	First issue
2	2017-12	Change in Affected Vehicles


Affected vehicles

Model year	Model	Engine	Transmission
2017, 2018	S90 (17-)	B4204T20, T23, T26, T27, T29, T31, T44 D4204T14, T23	TG-81SC TG-81SC AWD
2017, 2018	S90L	B4204T23, T27, T44	TG-81SC TG-81SC AWD
2017, 2018	V90 (17-)	B4204T23, T26, T27, T29, T31, T44 D4204T14, T23, T4	TG-81SC TG-81SC AWD
2017, 2018	V90 Cross Country	B4204T20, T23, T26, T27, T29 D4204T14, T23	TG-81SC TG-81SC AWD
2018	XC60 (18-)	B4204T20, T23, T26, T27, T29, T44 D4204T14, T23	TG-81SC TG-81SC AWD
2016, 2017, 2018	XC90 (16-)	B4204T20, T23, T26, T27, T29 D4204T11, T14, T23, T6	TG-81SC TG-81SC AWD

Orientation view



Color symbols




Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.

- 1 . Used for focused component, the component with which you will do something.
- 2 . Used as extra colors when you need to show or differentiate additional parts.
- 3 . Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4 . Used when the component is not fully removed from the vehicle but only hung to the side.
- 5 . Used for standard tools and special tools.
- 6 . Used as background color for vehicle components.


Removal

Note! Orientation view


The graphic shows the back of the component.



Remove the marked part.




Check



- 1 . Disconnect the connector.
- 2 . Connect the connector.
- 3 . **Caution! Check that the connector(s) is/ are properly connected.**

Installation



Install the marked component.