



Countries: AUSTRALIA, CANADA, UNITED STATES **Document ID:** IK1201260
Availability: ISIS, IsSIR **Revision:** 15
Major System: ENGINES **Created:** 1/21/2015
Current Language: English **Last Modified:** 10/29/2018
Other Languages: [Français](#), [Español](#) **Author:** Allan Hertko
Viewed: 5705

[Less Info](#)
[Hide Details](#)

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 13	Not Helpful 3
---------------	------------------------	---	----------------------	-----------	----------------------	-------------------	----------------------

Title: 2015+ N13 Cylinder Pack - Update for Excessive Lubrication Oil Consumption

Applies To: 2015+ N13 ESN: 4400000-4401769

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

10/29/2018- Changed diagnostic steps for oil consumption
 06/22/2018 - Added French and Spanish translation
 06/14/2018- Added links to IK 1201391 and WPL-18002G
 04/03/2018 - Changed Owner
 03/26/2018 - Feedback response

DESCRIPTION

Certain N13B engines ranging with engine serial numbers **4400000 - 4401769**, can experience higher than normal oil consumption due to carbon packing and build-up within the top ring lands of the piston. An updated cylinder kit is now available to address this condition. The updated liner incorporates a removable anti-polish ring (APR) at the top of the liner. The purpose of the anti-polish ring is to scrap carbon from the top ring lands keeping the secondary and compression rings from sticking and free during engine operation.

NOTE:

Check warranty repair history prior to performing this procedure within the Service Portal. If the engine has been upgraded with APR cylinder kits and is experiencing oil consumption, do not proceed with this article contact Tech Services.

NOTE:

APR liners cannot be mismatched with standard liners. If for any reason an APR liner needs to be installed within an engine with standard liners, all 6 liners will need to be updated to APR liners.

SYMPTOM(s)

Excessive Lubrication Oil Consumption (as defined by the diagnostic manual)

SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number
Tool, Piston Cope	12-146-01
	ZTSE2536

Cylinder Sleeve Puller	
Socket, Head Bolt (E24 Torx)	ZTSE4787
Socket, External Torx (E18)	ZTSE4835
Tap, M18x2 Bottoming (Head)	ZTSE4855
Bracket, Cylinder Head Lifting	12-342-03
Set MaxxFace 11&13 Cap & Plug	ZTSE4891

SERVICE PARTS INFORMATION

NOTE:

The following component inspections and/or replacements are NOT covered under warranty for this repair:

- Oil Pump
- Main Bearing
- Turbo
- Fuel Injector
- Oil Cooler
- Engine Oil (Recommended to replace at time of maintenance interval)
- Engine Coolant
- Cylinder Head

Any additional parts that are replaced will be considered customer responsibility.

NOTE:

The parts listed below are to be replaced under warranty during the warranty period. This is an update to correct the symptom of oil consumption on 2015+ N13 engine and is not considered a overhaul. The parts listed below are the only parts covered for this symptom.

CAUTION:

The N13 Engine has two different cylinder liners available in the Parts Catalog. It is important to verify that the most up-to-date liner is being installed. Follow the parts listed below.

Kit Description	Part Number	Quantity Required	Notes
KIT, CYLINDER HEAD REMOVAL	2515548C91*	1	
GASKET, 13L CYLINDER HEAD	62039010402*	1	
GASKET,OIL PAN	3003425C2*	1	
KIT, OIL FILTER	3007498C94*	1	
KIT, PSTN SLV & RING (718 13L)	2514508C91*	6	

KIT, 745 CONNECTING ROD BEARING- 1 CYLINDER	2513433C91*	6	*SEE CAUTION NOTE BELOW*
ROD BOLTS	62904900079*	12	
PICKUP TUBE SEAL O-RING 32 X 5	06569361612*	1	
TUBE ASSEMBLY TURBOCHARGER OIL SUPPLY	3018397C93*	1	
GASKET	2601233C1	2	Only used if aftertreatment is being serviced - DOC/DPF Gaskets
GASKET 4" EXH PIPE FLANGE	3846392C1	1	Only used if aftertreatment is being serviced - DOC Outlet gasket

NOTE: Items marked with an asterisk (*) are required.

DIAGNOSTIC STEP(s)

Perform the following diagnostic steps 1-5 listed in Engine Lubrication Symptoms section 6.3 Engine Oil Consumption located within the [2015 N13 Engine Diagnostic Manual](#) . Please submit your test results into a case file do not go any further with testing.

REPAIR STEP(s)


Follow: [2015 N13 Engine Service Manual](#) for base engine repairs.

CAUTION:

13L connecting rod bolt torque is CRITICAL. Apply a light amount of clean 30W engine oil to the underside of the new rod bolt head and threads. Follow the torquing procedure EXACTLY as written in the latest Service Manual using a calibrated torque wrench.

CONNECTING ROD BEARING SERVICE INFORMATION

The 2513433C91 rod bearing set contains a stronger polymer coated upper bearing which is darker in color. This bearing replaces the former 3004714C91 and has been in service since 2015. The coating was added due to increased cylinder pressures found in the 2015 N13. There are no dimensional changes in the bearing, and it is backward compatible to all MaxxForce and N13 engines.



CONNECTING ROD TORQUE PROCEDURE BEST PRACTICES

[IK1201391 2013-2015 N13 Required Torque Wrench to Complete Connecting Rod Bolt Torque Procedure](#)

- Always use new rod bolts
- Apply a **LIGHT** coating of engine oil to the threads and underside of the bolt head prior to installation. Do not dip the bolt in oil.
- Never set the rod or rod cap on the fractured mating faces.
- Clean the fracture faces, rod bearing saddles, bolt threads, and crank journal with cleaner such as Brake Clean, then blow dry with filtered air.
- **NEVER** use a rag or towel to wipe the fractured rod mating faces.
- **Use clean engine oil or Lubriplate #105 to lubricate the new bearings.**
- Follow IK1201391, torque bolts **BY HAND** in all three steps exactly as published in the Service Manual and IK article. Do not short cut by using unapproved methods.
- Do not use extensions on the torque wrench.
- It is critical to torque bolts on each cap evenly to the initial 22 ft.-lbs. before advancing to the next value. This will properly seat the cap to the rod. Do not fully torque one side then the other.
- Check the Service Manual regularly for procedural changes.
- Do not rotate crankshaft until connecting rod bolts are fully torqued as this may cause bearing to rotate in place.
- Lubricate the oil pick up tube and O-ring prior to assembly.
- Ensure the oil pick up tube is fully seated in the engine block. If not, aeration and oil pressure loss can occur causing severe damage to the engine.

WARRANTY INFORMATION

Warranty Claim Coding:

Group:	12000 - ENGINES
Noun:	192 - Sleeve, Cylinder

Standard Repair Time(s):

Description	Chassis	Engine	SRT	Notes
-------------	---------	--------	-----	-------

12 - PISTON AND/OR SLEEVE (I-6), REPLACE	Models, ALL	N13	A12-1192U	ONE
			A12-1192US-11 EACH ADDITIONAL	
12 - CYLINDER HEAD OR REPLACE GASKET (13L), R & R AND/OR REPLACE	Models, ALL	N13	A12-1342UT	

[WPL 18-002G- Required Use of New Torque Wrench](#)

All repair orders dated February 5, 2018 or later will require torque wrench data to be uploaded into the iApprove case file system for all N13 APR repairs. **A potential warranty chargeback can occur if the torque wrench data is not downloaded into the iApprove.**

OTHER RESOURCES

[Master Service Information Site](#)

 Hide Details

Feedback Information

Viewed: 5704

Helpful: 13

Not Helpful: 3

No Feedback Found

Copyright © 2018 Navistar, Inc.