

Technical Journal

TITLE:

Replacement of ERAD components

REF NO: TJ 33358.3.0	ISSUING DEPARTMENT: Technical Service		ARKET: s and Canada
3 US 7	PARTNER: '510 Volvo Car USA	ISSUE DATE: 2018-05-18	STATUS DATE: 2018-05-21
FUNC GROUP: FUNC DESC: 4600 Rear axle, drive shaft		Page ⁻	1 of 23

"Right first time in Time"

Attachment

File Name	File Size
TJI-509127-1_1_2_en-US.pdf	6.1204 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	('hassis range	Struc Week Range
246	BR	B1FPHEV					2018-9999		-	201717-209952
256	BC	B1BPHEV					2016-9999		-	201526-209952
256	BR	B1FPHEV					2018-9999		-	201717-209952

CSC Customer Symptom Codes

Code	Description			
YR	Drive mode "AWD"/Disengages automatically/Not available			
56	Drive mode "OFF ROAD"/Disengages automatically/Not available			
53	Driving, Twin Engine/Propulsion using electric motor not possible			
55	Driving, Twin Engine/Propulsion using combustion engine/Always active/Active too often			
AJ	Driving/Poor performance/lacks power			
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication			
8N	Driving/Unusual noise/Unsure when/at all times			
D2	Front/rear axle/Unusual noise			

Technical Journal 33358.3.0



VST Operation Number

VST Operation Number	Description
98210-2	ERAD transmission, replacement

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
IEM	P286F00	Intermittent
IEM	P286D00	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

*This journal is re-written in its entirety.

The ERAD (Electrical Rear Axle Drive) consists of two main parts, a transmission and an electrical motor.

To determine if the transmission or the complete ERAD needs to be exchanged follow instructions under "Service"

Instructional film is included as attachment, mp4.

The repair method is included as attachment, pdf.

SERVICE:

If the customer is driving in electric mode and experiences noise from the rear that increase with vehicle speed (that corresponds to the electrical motor speed) it is an electrical motor issue.

In this case the complete ERAD is to be exchanged.

No DTC(s) are set for this issue.

If the customer experiences hesitation when the electrical motor should be engaged or no electrical motor engagement at all, the transmission part needs to be exchanged.

This fault results in Clutch DTC(s) as indicated in the list, and a message in DIM (Driver Information Module) "Hybrid system failure, Service required".

ERAD transmission is ordered according to normal routines. ERAD transmission Part No. 32240142.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 4600. For vehicles with ERAD Clutch DTC(s) but no noise complaints while driving, please submit a Vehicle Report and sub concern area "Support not needed".

To view TJ attachment continue to next page. This TJ has one attachment.

Page 2 of 23 2018-05-21

Title Replacement of ERAD components

Ref No US33358.3.0 en-US

Issuer Technical Service

Partner 3 US 7510 Volvo Car USA

Func Group 4600

Func Desc rear axle, drive shaft

Status Released
Status 2018Date 05-18
Issue 2018Date 05-18
Reference

Attachment

File Name			File Size	
TJI-509127-1	1	2	en-US.pdf6.1204 M	В

Vehicle Type

Турє	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246	BR	B1FPHEV					2018- 9999		-	201717- 209952
256	ВС	B1BPHEV					2016- 9999		-	201526- 209952
256	BR	B1FPHEV					2018- 9999		-	201717- 209952

CSC Customer Symptom Codes

CSC	customer Symptom codes
Code	Description
YR	Drive mode "AWD"/Disengages automatically/Not available
56	Drive mode "OFF ROAD"/Disengages automatically/Not available
53	Driving, Twin Engine/Propulsion using electric motor not possible
55	Driving, Twin Engine/Propulsion using combustion engine/Always active/Active too often
AJ	Driving/Poor performance/lacks power
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication
8N	Driving/Unusual noise/Unsure when/at all times
D2	Front/rear axle/Unusual noise

VST Operation Number

VST Operation No.	Description	
98210-2	ERAD transmission,	replacement

DTC Diagnostic Trouble Codes

ECU	DTC	Fault Type
IEM	P286F00	Intermittent
IEM	P286D00	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Description:

*This journal is re-written in its entirety.

The ERAD (Electrical Rear Axle Drive) consists of two main parts, a transmission and an electrical motor.

To determine if the transmission or the complete ERAD needs to be exchanged follow instructions under "Service".

Instructional film is included as attachment, mp4.

The repair method is included as attachment, pdf.

Service:

If the customer is driving in electric mode and experiences noise from the rear that increase with vehicle speed (that corresponds to the electrical motor speed) it is an electrical motor issue.

In this case the complete ERAD is to be exchanged.

No DTC(s) are set for this issue.

If the customer experiences hesitation when the electrical motor should be engaged or no electrical motor engagement at all, the transmission part needs to be exchanged.

This fault results in Clutch DTC(s) as indicated in the list, and a message in DIM (Driver Information Module) "Hybrid system failure, Service required".

ERAD transmission is ordered according to normal routines. ERAD transmission Part No. 32240142.

Vehicle Report:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 4600.

For vehicles with ERAD Clutch DTC(s) but no noise complaints while driving, please submit a Vehicle Report and sub concern area "Support not needed".

To view TJ attachment continue to next page. This TJ has one attachment.



Volvo Car Customer Service

TJ Instruction VCC-509127-1

Title	ERAD transmission	Page	1 (19)
Action	Replacement	Operation number:	98210-2

Issue	Date	Reason
1	2018-01	First issue

Affected vehicles

Model year	Model	Engine	Transmission
2018	S90L	B4204T28, T35	TG-81SC
2018	XC60 (18-)	B4204T28, T34, T35	TG-81SC
2016, 2017,	XC90 (16-)	B4204T28, T34, T35	TG-81SC
2018			

Materials

Materials	Qty.	Part No.	Notes
Strip clamp	1.0	983750	


Special tools

Description	Part No.	Notes	
Fixture	999 7689		
FLOOR STAND (TO FIXTURES)	999 2520	Substitute with an appropriate stand as necessary	

Equipment

Designation	Part No.
Plastic mallet	
Circlip pliers, internal	

Color symbols



Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.

- Used for focused component, the component with which you will do something.
- 2. Used as extra colors when you need to show or differentiate additional parts.
- Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4 . Used when the component is not fully removed from the vehicle but only hung to the side.
- 5. Used for standard tools and special tools.
- 6 . Used as background color for vehicle components.

Removal


Follow instructions for lifting points body frame , refer to:

Specifications, mechanical

8 - Body and interior


81 - Body frame

810 - general




Warning! Be prepared to collect escaping fluid.

Remove the screw.




Caution! The fluid must be allowed to escape until a continuous flow changes into single drops.



Note! Make sure that the component is clean and free of foreign material.

Remove the swarf.



Install the screw.

Torque:


ERAD Oil drain plug, 20 Nm


Remove rear axle, electric erad, refer to:
Removal, replacement and installation

4 - Power transmission


46 - Rear axle, drive shafts

465 - final drive (front and rear)







Special Tool: T9992520, FLOOR STAND (TO FIXTURES)




Remove the screw.
Remove the cable harness clips.
Remove the marked part.




Remove the screw. Lift the marked component up





Disconnect the connector. Remove the marked part.



Fold marked part to one side.









Note! Make sure that locating studs remains in the timing gear casing.


Remove the marked part.

Use: Plastic mallet






Old sealing.



Caution! Make sure that the wiring harness does not catch.


Note! Note the position of the component before removal.


Remove the part carefully Remove the marked part.



Remove the marked part.


Use: Plastic mallet





Release the lock. Remove the marked part.


Use: Circlip pliers



Note! Check the component. if any damage is shown, the whole complete ERAD is to be exchanged.

Note! Make sure that the component is clean and free of foreign material.

Installation




Caution! Make sure that the component is positioned correctly.


Install the catch.

A click confirms that the component is in the correct position.


Use: Circlip pliers




Note! As an alternative if a tool is not at hand, use two bolts M8 x 60 mm with heads cut off.




Note! Use a new seal.




Caution! Make sure that the component is correctly located on the locating dowels.






Caution! Make sure that the wiring harness does not catch.


Pull the wiring through.



Note! Make sure that the installation marks are aligned.




Connect the connector.




Install the marked component. Install the screw.

Torque:


Solenoid Connector, to ERAD housing , 10 $\ensuremath{\mathsf{Nm}}$




Note! Use a new seal.




Caution! Make sure that the component is correctly located on the locating dowels.



Caution! Make sure that the component is correctly located on the locating dowels.




Remove the Special Tool.



Install the screws.
Tighten the bolts.

Torque:

M8 , 24 Nm



Install the marked component.

Install the screw.

Fasten the wiring harness using the existing clips.

Torque:

Position Sensor Connector, to ERAD housing , 10 Nm $\,$

Install electric rear axle drive ERAD, refer to: Removal, replacement and installation

4 - Power transmission

46 - Rear axle, drive shafts

465 - final drive (front and rear)

Perform ERAD oil level check, refer to:

Cleaning, Inspection and Adjustment

4 - Power transmission

46 - Rear axle, drive shafts

465 - final drive (front and rear)