

Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected:

P11: 12C, 12C Spider, 650S, 650S Spider, 625C, 625C Spider

P13: 570S, 570S Spider, 540C, 570GT

Location: Electrical - Infotainment (AIS)

Concern: Hard buttons on IRIS screen inoperative

Condition: After replacement of the IRIS screen, the hard buttons are not operating

Diagnostic Trouble Codes

N/A

Measure

Care Point: The process outlined below is complementary to the repair instructions. Always follow SIS instructions to install new hardware.

1. Once a new IRIS screen has been installed, turn the ignition ON and connect a USB keyboard to the AUX USB module.
2. Press F1 on the keyboard to access the Settings menu.
3. Select Advanced Settings and then Privacy.
4. Select Factory Data Reset followed by Reset and then Erase Everything.
5. The system will now reboot. Factory Data Reset is completed once the system has returned to the Standby Screen.
6. During Factory Data Reset the system updates the software of the new IRIS screen so that the hard buttons become operative.
7. Disconnect the USB keyboard and check the operation of the display including the hard buttons.

MTI Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.