# GLOBAL SAFETY FIELD INVESTIGATIONS DCS4927 URGENT - DISTRIBUTE IMMEDIATELY

Date: December 11, 2018

- Subject: N182195380-01 Service Update Harsh Downshift After Extended Driving in High Gears
- Models: 2019 Chevrolet Silverado 1500 (New Model) 2019 GMC Sierra 1500 (New Model)
- To: All General Motors Dealers

A note has been added to the Service Procedure. Please discard all copies of N182195380.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS

# **Service Update** N182195380 Harsh Downshift After Extended Driving in High Gears



## Release Date: December 2018

#### Revision: 01

**Revision Description:** A note has been added to the Service Procedure. Please discard all copies of N182195380.

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Silverado 1500 (New Model)	2019	2019		
GMC	Sierra 1500 (New Model)				

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2019 model year Chevrolet Silverado 1500 (New Model) and GMC Sierra 1500 (New Model)				
	vehicles equipped with a 10-speed transmission may have a condition where the downshift becomes				
	firm after extended highway driving.				
Correction	Recalibrate the transmission control module (TCM).				

#### Parts

No parts are required for this repair.

### Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9104158*	Transmission Control Module Reprogramming with SPS (Includes Transmission Service Fast Learn Procedure)	0.7	ZFAT	N/A
9104219**	Module Programming Not Required	0.2	ZFAT	N/A

\* To avoid warranty transaction rejections, the SPS Warranty Claim Code must be entered when submitting this transaction. Note that if multiple modules are reprogrammed, all claim codes must be entered with a comma separating each code.

\*\* SPS Warranty Claim Code is NOT required when submitting this transaction.

# Service Procedure

Note: Carefully read and follow the instructions below.

- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will
  interrupt programming. When required, install a GM Authorized Programming Support Tool to maintain system
  voltage. Refer to: <u>https://www.gmdesolutions.com/</u> for further information. If not available, connect a fully charged
  12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Turn OFF or disable systems that may put a load on the vehicle's battery such as; interior lights, exterior lights (including daytime running lights), HVAC, radio, etc.
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.

**Caution**: If the Same Calibration/Software Warning is noted on the SPS Controller screen, do NOT attempt to program the module. No further action is required. Refer to the Warranty section of the bulletin and use labor operation code 9104219, Module Programming Not Required.

**Note:** After programming has been completed, be sure to turn the ignition off and let all modules go to "sleep" for 2 minutes.

# Service Update N182195380 Harsh Downshift After Extended Driving in High Gears



- 1. Reprogram the transmission control module. Refer to K71 Transmission Control Module: Programming and Setup in SI.
- 2. Record SPS Warranty Claim Code on job card for warranty transaction submission.

## **Dealer Responsibility**

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



We Support Voluntary Technician Certification