



Technical Journal

TITLE:
Infotainment System Reboots while driving (blank screen)

REF NO: TJ 31602.9.1	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-10-01	STATUS DATE: 2018-10-08
FUNC GROUP: 3930	FUNC DESC: Equipment for entertainment (radio/TV/VC)	Page 1 of 3	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-9999		-	201835-999952
225							2019-9999		-	201817-999952
234							2017-2017		-	201617-201716
235							2017-9999		-	201624-999952
236							2017-9999		-	201646-999952
238							2018-9999		-	201717-999952
246							2018-9999		-	201717-999952
256							2016-9999		-	201505-999952
536							2019-9999		-	201746-999952

CSC Customer Symptom Codes

Code	Description
32	Infotainment/System reboots
2E	Audio other/Keypad on center console does not work
DO	Audio other/Audio unit (complete) does not work
FC	Audio other/Other audio problems
6B	Buttons/control knobs on centre console (Media, communication and navigation)/No/reduced/incorrect function
7N	Navigation/Other navigation problems



VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading.

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

* New IHU software released 10/1/2018

* Vehicle type 224 and 225 added

This TJ Replaces TJ 31295 dated 12/15/2017

IHU = Infotainment Head Unit

CCD = Center Console Display

DIM= Driver Information Module

The customer may report that the infotainment system in the vehicle re-starts or reboots intermittently while driving.

When this happens the CCD and the center area of the DIM will go blank for a few moments and then start back up as if the vehicle has just been started up.

The customer may also notice that the infotainment system is not responding as normal (ex.- long response time) just before this occurs.

When the system reboots, some customer settings may change back to a previous setting (ex.- navi destination, climate settings, radio station, etc.)

Follow the instructions under Service to repair this condition.

*New IHU software is available as of 10/2/2018 to improve the system stability. Please follow the instructions under Service.

SERVICE:

Do NOT replace the IHU for this symptom unless directed to in a Vehicle Report.

If the above symptom(s) occur, the IHU needs to be upgraded. Please perform a *Total Upgrade* in accordance with TJ 31543.

(The improved IHU software is included in the *Total Upgrade*)

Also make sure any installed in-car apps are of the latest version by checking for updates in the Download Center.



If the IHU software and in-car apps all have the latest version and the customer still experiences a rebooting symptom: follow instructions in TJ 33575, procedure #4 for retrieving **Reset** log files from the IHU and attach them to a Vehicle Report following the instructions below.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support Needed", use function group 3930.

Ask the customer how frequently this symptom occurs and if any special circumstances are noted in relation to the symptom such as if it only happens during use of certain functions or when using a specific app or source. Include this information in the Vehicle Report.

Compress any log files using file compression software such as WinZip and attach them to the Vehicle Report.