Mazda North American Operations Irvine, CA 92618-2922



Subject: APPLE CARPLAY™ / ANDROID AUTO™ FREQUENTLY ASKED QUESTIONS (FAQ)	Service Alert No.: SA-001/19	
	Last Issued: 01/04/2019	

# **BULLETIN NOTES**

This Service Alert supersedes the previously issued SAs listed below. The changes are noted below in Red.

Previously Issued SAs:	Date(s) Issued
SA-046/18	11/6/18 and 10/24/18

### APPLICABLE MODEL(S)/VINS

2014-2018 Mazda3 2016-2018 Mazda6 2016-2019 CX-3 2016-2019 CX-5 2016-2019 CX-9 2016-2019 MX-5

## DESCRIPTION

## Frequently Asked Questions (FAQ)


FAQ	Answer
The installation instructions are missing from the Smartphone Screen Mirroring Kit (Apple CarPlay™/Android Auto™ retrofit installation kit)	Click the model below for the Installation instructions: 1. Mazda3 2. Mazda6 3. MX-5 4. CX-3 5. 2016 CX-5 6. 2017-2018 CX-5 7. CX-9
(annot operate Annie (arPlav)	Refer to MGSS online CANNOT OPERATE Apple CarPlayTM [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
ICannot operate Android Auto™	Refer to MGSS online CANNOT OPERATE Android AutoTM [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]

Page 1 of 8


Cannot operate Android Auto™ or some functions do not work.	<ul> <li>During Android Auto set up, all permissions and requests may have not been accepted by the customer.</li> <li>Do the following: <ol> <li>Detete Android Auto from the customers phone.</li> <li>Unpair the customers phone from the vehicle.</li> <li>Connect the customers phone to the smartphone USB port.</li> </ol> </li> <li>Note: Use a high-quality, certified USB cable.</li> <li>During Android Auto set up, accept all permissions and requests.</li> </ul>
Where do I find support for Apple CarPlay™	Go to Apple Support
Where do I find support for Android Auto™	Go to Android Auto Help
What phone do I need to operate Apple CarPlay™	<ol> <li>iPhone 5 or above</li> <li>For best performance, update iPhone to the latest iOS version</li> <li>Apple Lightning<sup>®</sup> to USB cable or a high-quality, certified USB cable</li> <li>Siri<sup>®</sup> must be enabled to use Apple CarPlay</li> <li>For additional information, go to Mazdausa.com -&gt; OWNERS -&gt; HOW TO USE -&gt; OWNER'S MANUALS -&gt; APPLE CARPLAY QUICK START GUIDE</li> </ol>
What phone do I need to operate Android Auto™	<ol> <li>Android phone running 5.0 (Lollipop) or higher</li> <li>Android 6.0 (Marshmallow) or higher is recommended</li> <li>High-quality, certified USB cable</li> <li>For additional information, go to Mazdausa.com -&gt; OWNERS -&gt;</li> <li>HOW TO USE -&gt; OWNER'S MANUALS -&gt; ANDROID AUTO QUICK</li> <li>START GUIDE</li> </ol>
Cannot operate Apple CarPlay™ or Android Auto™	<ol> <li>Confirm that the USB cable is connected to the port labeled with a smartphone icon.</li> <li>Image: Confirm that a high-quality certified USB cable is used.</li> </ol>

displayed in the menu.	<ol> <li>Waze Requirement - iPhone iOS 12.0 or higher and Waze version 4.43.4 or higher.</li> <li>Google Maps Requirement - iPhone iOS 12.0 or higher.</li> </ol>
Cannot update CMU software after USB Cable Set Kit (P/N C922-V6-605) installation.	This may be caused by USB Cable Set Kit (P/N C922-V6-605) installation error. The hardware was installed before CMU software update by USB flash drive. <u>Failure:</u> In some cases, the CMU will not recognize the new HUB unit, so CMU software update by USB flash drive is not possible. <u>Recovery:</u> Proceed to Repair Procedure.
	Confirm that the Navigation SD Card was transfered from the old USB HUB unit to the new USB HUB unit.

Page 3 of 8



Page 4 of 8



#### Page 5 of 8


	This may be caused by Apple iPhone IOS 12.0 update. The customer sets a navigation destination on Google Maps, then sets a navigation destination on MAZDA CONNECT, double voice navigation is heard through the vehicle speakers. <b>Example:</b>		
speakers.	Apple iPhone software IOS 12.0 update		
		NG	
	CONNECT destination set	(double voice)	
	MAZDA CONNECT destination set> Google Maps destination set	Good	
	<b>Repair</b> - This is an Apple IOS 12.0 issue. No vel necessary.	nicle repair is	

# **REPAIR PROCEDURE**

(Cannot install CMU software after USB Cable Set Kit (P/N C922-V6-605) installation)


1. Disconnect the new USB HUB unit and the new USB cables from the CMU.

Page 6 of 8



2. Connect the old USB HUB unit and the old USB cable to the CMU.

Page 7 of 8



- 3. Update the CMU to software version 70.00.021B or later by USB flash drive.
- 4. Remove the old USB HUB unit and disconnect the old USB cable from the CMU.
- 5. Re-connect the new USB HUB unit and the new USB cables to the CMU.

#### Page 8 of 8