



SI B11 18 18
Engine

January 2019
Technical Service

SERVICE ACTION: ALPINA B7 WITH N63R ENGINE – CHECK AND REPLACE OIL FEED LINES AND THE MAP THERMOSTAT ELECTRICAL CONNECTOR

New information provided by this revision is preceded by this symbol  .

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

This Service Information bulletin replaces SI B11 18 18 dated **October 2018**

What's New:

- Warranty labor operation table updated

MODEL

G12 (ALPINA B7 Sedan)

AFFECTED VEHICLES

This Service Action involves 224 G12 ALPINA B7 vehicles produced from January 2016 to February 2017.

Vehicles which require this Service Action to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

SITUATION

This bulletin describes the procedures to inspect and if necessary replace the following components:


- Turbo charger oil feed lines (leaking)
- Map thermostat and electrical harness (corrosion)

PROCEDURE

SECTION 1: INSPECT AND REPLACE THE TURBOCHARGER OIL FEED LINES


Turbocharger oil feed line overview:






The oil feed line locations are shown with red highlight

Oil feed line construction overview:



1. Stainless steel flexible section. This is the new design and should not be replaced.



2. Black rubber flexible section. This line should be replaced.

1. Remove and install the engine acoustic cover as per Repair Instructions 11 12 070 "Removing & installing/replacing the acoustic cover"



2. Check the exhaust turbocharger oil feed line on bank 1.

If the flexible section of the feed line is made of braided stainless steel (see arrows) then take no further action. **Do not replace the line.**

If the flexible section is black rubber then the oil feed line will need to be replaced.

Refer to Repair Instruction 11 42 200 "Remove and install / renew the oil feed line for the exhaust turbocharger N63O2"
Do not remove the turbochargers!

3. Check the exhaust turbocharger oil feed line on bank 2.


If the flexible section of the feed line is made of braided stainless steel (see arrows) then take no further action. **Do not replace the line.**

If the flexible section is black rubber then the oil feed line will need to be replaced.

Refer to Repair Instruction 11 42 200 "Remove and install /



**renew the oil feed line for the exhaust turbocharger N63O2”
Do not remove the turbochargers!**



4. Only if the oil feed lines were actively leaking oil.

Check the engine block (V-space) for engine oil residue and clean as needed.

If there is leakage, the exhaust system, both exhaust turbochargers, the lower heat shield, the complete exhaust manifold and the oil-to-coolant heat exchanger needs to be removed to clean this area.


Refer to the following repair instructions:

11 62 060 “Removing and installing/replacing the left exhaust manifold (bank 5-8)”

11 62 065 “Removing and installing/replacing the right exhaust manifold (bank 1-4)”

11 44 000 “Removing and installing/replacing the oil-to-coolant heat exchanger”


Wipe dry with a shop towel and rinse the residual oil with cleaner via the drain hole and flush it out (see arrow).



5. If the lower transmission housing also has oil residue present then it has to be cleaned via the opening (1). To do so, remove the sealing cap (1) and sealing cap (2) and flush out the excess engine oil residue. The sealing cap (2) may be located on the left or the right side of the transmission housing.

Reinstall both sealing caps when finished.

Section 2: Inspect and Replace Map Thermostat and Electrical Harness



1. Locate the Map Thermostat Electrical Connector (1).

2. Remove the connector and check the pins in the connector



for traces of water or corrosion.

Example: This connector is already corroded.

If the pins in the connector are corroded, the engine wiring harness and the characteristic map thermostat need to be replaced.

Refer to the following Repair Instructions:

12 51 300 "Removing and installing/replacing the wiring harness section of engine ignition control for cylinders 1-4".

11 53 000 "Removing and installing/replacing the coolant thermostat".

If no corrosion is found then do not replace any parts.

PARTS INFORMATION

Refer to the ETK and the applicable repair instructions for one-time use fasteners and/or component information regarding additional or replacement screws, gaskets, and seals that need to be installed and claimed.

Section 1 Parts List:

Part Number	Description	Quantity
11 42 7 934 655	Exhaust turbocharger oil feed line, CYL 5-8	1
11 42 7 934 654	Exhaust turbocharger oil feed line, CYL 1-4	1
07 11 9 963 072	Sealing rings for oil feed line	4
07 11 9 963 201	Sealing rings for coolant line / exhaust turbocharger	6
07 14 7 413 212	Combination Allen bolt	2 (if needed)
13 71 7 601 067	Clean air pipe seal	2 (if needed)
11 42 8 627 197	Oil feed line banjo bolt	2
31 10 6 870 648	Screw with disc for stiffening plate	12 (if needed)
07 14 9 390 155	Screw with disc for strut brace	2
51 71 6 966 566	Screw with flange for strut brace	6
07 11 9 905 147	Screw with washer for bulkhead strut brace	4
11 15 1 726 339	Hose clamp for coolant line	2

Section 2 Parts List: (The failure rate is less than 2 percent, do not over order)

Part Number	Description	Quantity
11 53 8 602 282	Characteristic map thermostat	1
12 51 8 654 414	Engine wire harness (Produced up to 10/2016 production)	1
or		
	Engine wire harness (Produced from 10/2016	


12 51 8 679 109	production)	1
-----------------	-------------	---

All repairs, as needed (Sublet code 4):

Part Number	Description	Quantity
82 14 1 467 704	Antifreeze	As needed per the Repair Instructions
83 21 2 365 950	0W-30 LL01FE (12 x 1 Liter case)	As needed
	or	
83 21 2 405 849	0W-30 LL01FE (209 liter drum)	As needed
	or	
83 21 2 449 994	0W-30 LL01FE (Tanker Delivery – Liters)	As needed


 **WARRANTY INFORMATION**

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

Defect Code:	0011950400	
Labor Operation:	Labor Allowance:	Description:
00 66 959	28 FRU	Checking oil feed lines of exhaust turbocharger and thermostat for cracks and moisture, replacing thermostat if necessary (Plus work)
Or:		
00 66 960	84 FRU	Checking oil feed lines of exhaust turbocharger; thermostat for cracks and connector for moisture and replacing an oil feed line (Plus work)
Or:		
00 66 961	96 FRU	Checking oil feed lines of exhaust turbocharger; thermostat for cracks and connector for moisture; replacing both oil feed lines (Plus work)
And, as necessary:		
00 66 962	62 FRU	Additional work, cleaning the engine block (V-space) and transmission housing (Associated work)
 And/or:		
00 66 963	AWD – 84 FRU; RWD – 85 FRU	Additional work, replacing the engine wiring harness and the characteristic map thermostat (Associated work)

And:

Sublet – Bulk Materials

Sublet Code 4	 Up to \$35.00	Reimbursement for the repair-related bulk materials (BMW part number, please do not use the part numbers for claim submission)
----------------------	---	--

Sublet reimbursement calculation for claiming the “used quantities” of repair-related bulk materials (BMW part numbers) is at dealer net plus your center’s handling.

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section.

One gallon (3.78 liters) of Antifreeze/Coolant provides 2 gallons or 8 quarts (7.57 liters) when mixed with water to create a 50/50 recommended mixture.

And, as applicable:

Alternative Mobility Solution (AMS) for Vehicle Owners

This Service Action repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Defect Code noted above as follows:

- Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to SI [B01 29 16](#) for additional information.

Posted: Wednesday, January 30, 2019

[Copyright ©2019 BMW of North America, Inc.]