				Countries:	AUSTRALIA, BAHAMAS, BOLIVIA, BRAZIL, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR EL SALVADOR, TRINIDAD AND TOBAGO, UNITEL STATES, URUGUAY, VENEZUELA, MEXICO, ARUBA, NICARAGUA, PERU, PUERTO RICO, Curaçao, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, KOREA, SOUTH KOREA, PANAMA, SOUTH AFRICA		Document ID:	IK0400063	
				Availability:	ISIS, Fle	etISIS, NotSIR		Revision:	11
Knowledge Base				Major System:	BRAKES	3		Created:	8/21/2009
	_			Current Language:	English			Last Modified:	1/15/2019
				Other Languages:	Portugue	ese,		Author:	William Knoth
				Viewed:	4450				
									Less Info
अ∀ Hide Details			С	oding Inform	ation				
Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	:	Provide Feedback	Helpful	Not	Helpful
GO		View My Bookmarks	*	-		Ţ	1324		448

Title: Brake pedal not returning and sticking slightly in the applied position

Applies To: All Models

CHANGE LOG				
Please refer to the change log text box below for recent changes to this article:				
01/15/2019 - Updated diagnostics to include Acoms verions updates				
12/10/2018 - Updated article to inclued possible faults codes 24-4 and 24-6.	^			
10/22/2018 - Updated troubleshooting steps	~			
07/26/2018 - Released article for all models	•			

DESCRIPTION

Brake lights staying on due to brake pedal not returning and binding.

SYMPTOMS

- Cruise control not working
- Brake lights staying on
- If conditions is present long enough, ABS fault setting (Bendix ABS only)

Diagnostic Trouble Code(s) & Dashboard Indicator Light(s):

Bendix Flash Code	SPN	FMI	Source Address	Description
24 4	1067	11	11	Primary and Secondary Circuit PS (PS1/PS2 Plausibility Error) Brake Demand
24 6	1067	7	11	PS Not Calibrated

PARTS INFORMATION

• M8 flat hardened flat washer (8.8 x 17 x 1.6mm) part number 934675R1.

TROUBLESHOOTING

Step	Action	Decision
1	DIAGNOSTIC: Check for faults in ABS controller.	Yes: Please proceed to step 2
	Are the fault codes 1067-11 (24-4) and or 1067-7 (24-6) active in the Bendix ABS controller?	No: Go to step 4.

Stop	Action	Decision
	Action	Decision
	DIAGNOSTIC: Ensure AComs version v6.16.5.2 or greater is being used. And that v6.16.5.0 has not been used to connect to the vehicle.	Yes: Proceed to step 3.
	Refer to <u>ACom 6.16.5.2 Release Notes</u> for more details.	
2	Has only only version 6.16.5.2 or greater been used?	No: Update AComs to the lastest version and reconnect to the vehicle. Follow on screen promotes.
Step	Action	Decision
	DIAGNOSTIC: With both the primary and secondary air tanks full and equal pressures. Open ACOMS and monitor the primary and secondary application pressure sensors.	Yes: Please proceed to step 4.
	Without the brakes depressed, pull up on the pedal and record the sensors readings. Are they both reading 0psi (+- 2 psi)? With the brakes are fully depressed. Are the two sensors reading full tank pressure?	No: Diagnose the pressure sensors and or pressure sensor's circuits.
Step	Action	Decision
4	DIAGNOSTIC: A light brake apply and a slow brake release may be needed to duplicate the brake lights hanging on. Are the brake lights on with no pressure being applied to the brake pedal?	Yes: Lift the brake pedal with your hand and release the pedal. If the brake lights turn off the proceed to the resolution.
	Are the prace lights on with no pressure being applied to the prace pedal?	If lights are still on, proceed to other switch, wiring and air system diagnostics. No: Lightly press the brake pedal and release.



RESOLUTION

Please click on the link below for detailed instructions for completing this repair

Pedal Repair Instructions - PDF Document

WARRANTY INFORMATION

Warranty Claim Coding:

Refer to the <u>Warranty Coding Manual for Group and Noun Codes</u>.

Standard Repair Time(s):

Refer to the <u>SRT Manual</u> for Repair Times

Alide Details	Feedback Information		
	Viewed: 4449		
	Helpful: 1324		
	Not Helpful: 448		
No Feedback Found			

Copyright © 2019 Navistar, Inc.