



Date: 09.01.2019

Model: Specific Evora 400
'18 Model Year VIN's

Number: 2019/01
Federal Market

Copy files should be maintained by:

Service Manager	Service Reception	Lotus Technicians	Parts Manager	
-----------------	-------------------	-------------------	---------------	--


TITLE:

Replacement of the rear tail lamps due to the possibility of incorrect illumination during the combined turn indicator and brake light operation.

REASON:

It has been noted that on a small number of Evora 400 vehicles, that when activated at the same time, the turn indicator function is not overriding the brake lamp illumination. This has resulted in the brake lamp still being illuminated at a lower intensity (instead of being extinguished) during the turn indicators 'off' cycle.

An investigation has found that incorrectly manufactured rear lamp assemblies, part number (B132M0196F) with a batch date of 18/05/18* are the cause of this issue.



Parts Required

Description	Part number	Qty/car
Lamp, outer, tail. turn, stop/tail	C132M0196F	2

*Note: Any B132M0196F part numbered lamp displaying a different batch date ARE NOT affected by this campaign action.

Lamp Identification

With the lamp(s) removed from the vehicle, the batch date label is adhered to the lamp housing, positioned opposite to the part number label.

ACTION:

Even if currently operating correctly, both the rear tail lamps of a vehicle affected by this campaign must still be replaced as a vehicle set (left and right hand side), as this fault is intermittent and may not occur until a later date, dependant upon vehicle or ambient conditions.

C132M0196F lamp assemblies are available to order using the parts system on Lotus Dealer Connect. Refer to service notes section MH.11 for information on rear tail lamp replacement.

- All affected Evora VIN's have been identified and are listed on page 2 of this bulletin as well as being displayed by campaign status if their VIN is entered on screen option DC611 of the Lotus Dealer Connect system, campaign number 2019/01.
- Please check and identify any affected VIN's from your inventory stock and dealer demonstrators and install the 'C' level lamps as soon as possible.
- Please check and identify any affected VIN's from customer records that you have on file.

CHARGES:

A warranty claim for 0.4 hours labor and 2 x C132M0196F lamps may be submitted on Lotus Connect, option DC603, Bulk Entry Campaign, enter campaign number 2019/01.

Ends

LOTUS CARS LIMITED



Evora 400 Vehicles in Serial Number Order Affected by Campaign 2019/01

SCCLMDVN6JHA21243
SCCLMDVN2JHA11244
SCCLMDVN4JHA11245
SCCLMDVN1JHA21246
SCCLMDVN8JHA11247
SCCLMDVNXJHA11248
SCCLMDVN7JHA21249
SCCLMDVN8JHA11250
SCCLMDVNXJHA11251
SCCLMDVN5JHA11254
SCCLMDVN7JHA11255
SCCLMDVN9JHA11256
SCCLMDVN6JHA21257
SCCLMDVN2JHA11258
SCCLMDVN4JHA11259
SCCLMDVN0JHA11260
SCCLMDVN2JHA11261
SCCLMDVNXJHA21262
SCCLMDVN6JHA11263
SCCLMDVN8JHA11264
SCCLMDVN7JHA11269
SCCLMDVN3JHA11270
SCCLMDVN5JHA11271
SCCLMDVN7JHA11272
SCCLMDVN9JHA11273
SCCLMDVN2JHB21274
SCCLMDVN2JHA11275
SCCLMDVN4JHA11276

LOTUS CARS LIMITED