



EMISSIONS RECALL

**CAB OVER ENGINE (COE) ECU AND DCU
SOFTWARE UPDATE**

**CAMPAIGN NO: AACR0
DATE: 2-14-2019
REFERENCE: QA-190212-N1**

SUBJECT VEHICLES: 18MY-20MY COE trucks equipped with a J05 engine

Note: *Refer to the appropriate Vehicle Identification Number in the warranty system to determine vehicle eligibility.*

5. Handling of Dealership Inventory

Under 40 Code of Federal Regulations § 1068.101, a dealer cannot sell, offer for sale, or introduce or deliver for introduction in interstate commerce a new motor vehicle when it is aware that the vehicle does not comply with an applicable Federal Motor Vehicle Safety Standard or contains a defect related to motor vehicle safety. A civil penalty of up to \$44,539 may be assessed for each engine or piece of equipment in violation. In addition, 49 Code of Federal Regulations §577.13 requires us to provide the following advisory: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

We request your assistance to ensure involved vehicles are identified and not delivered prior to performing the remedy.

OVERVIEW:

Software updates are required for the Engine ECU (Engine Control Unit) and DCU (Dosing Control Unit) modules. These updates are intended to address the following items.

- 1) DPF Feedback monitor (P24A1 or P24A0)
- 2) SCR Feedback monitor (P2BAE)
- 3) Urea Tank Heater Valve Stuck Open monitor (P20B2)
- 4) All Injector (#1-#6) Misfire (P0300)




BEFORE YOU BEGIN:

- Read and understand all instructions and procedures before you begin the work.
- Read and follow all **NOTICES, WARNINGS, and CAUTIONS** set forth in this publication. These alerts help to avoid damage to components, serious personal injury, or both.
- Park the vehicle on a level and solid surface and apply the parking brake.
- Confirm the engine is stopped, the starter switch is in the off (LOCK) position, and the key is removed.
- Wear safety glasses to prevent eye injuries.
- Place wheel chocks in front of and behind all wheels.
- **NOTICE:** Before beginning these procedures, you **MUST** install a battery charger on the vehicle to ensure battery power does not go low during reprogramming.
- **NOTICE:** Before beginning these procedures, you also **MUST** be certain that the laptop battery is fully charged, or a remote AC power supply is connected to the laptop to ensure the battery power does not go low during reprogramming.

VEHICLE PREPARATION:

1. Park the vehicle on a flat, level and solid surface.



2. Confirm the engine is stopped, the ignition switch is in the off (LOCK) position, and the key is removed.



3. Apply the parking brake.



4. Chock all of the wheels.



Engine ECU Software

PART NUMBER	MODEL YEAR	ENGINE SERIES	QUANTITY
89663-E4046A	2018 Diesel	J05ETP	As Required By VIN
89663-E4056A	2018 Hybrid	J05EUG	
89663-E4644C	2019-2020 Diesel	J05ETP	As Required By VIN
89663-E4654C	2019-2020 Hybrid	J05EUG	

DCU Software

PART NUMBER	MODEL YEAR	QUANTITY
89550-37245	2018, 2019, 2020	As Required By VIN

PC PREPARATION

PC Power Management

CAUTION: Disable the computer features listed below. Failure to disable these features may severely damage the vehicle's control modules.

1. Screen saver
2. Energy saving features
 - a. Monitor
 - b. Hard disks
 - c. System standby



NOTICE: The illustrations above depict what you will see on your computer screen with regard to the features which must be disabled. The location on the screen of the features to be disabled will vary, however, based upon the operating software. Consult your IT (Information Technology) department as required.


DCU & ECU REPROGRAMMING PROCEDURE

CAUTION: Two modules will be reprogrammed during this procedure. A battery charger **MUST** be installed on the vehicle to ensure battery power does not go low during reprogramming or damage to these modules may occur.


1. Prepare a DXII compatible interface, such as the Denso DST-i or the Nexiq USB Link 2 to perform this reprogramming procedure.

To assemble the interface cable, perform the following steps.


- (1) Connect the DLC (Diagnostic Link Connector) cable to the interface.
- (2) Connect the USB Cable to the interface.
- (3) Connect the USB connector to the USB port on your computer.




2. Connect the DLC cable to the vehicle's DLC connector. The DLC connector is found under the dash on the left side of the steering column.



3. On your computer, locate the “Hino DX2” icon and open it.




4. Hino DX2 will prompt you for a “User ID” and “Password”. Enter your User ID-, and password and then select the “Login” icon. Verify that the DX2 has software version 1.1.19.2 or later.




5. Insert the ignition key into the starter switch and turn the key to the “ON” position.



6. Select the “Reprogramming” icon.



7. Select “300 Series” under the “Vehicle Classification” drop down menu.



8. Select “DCU (Doser)” under the “System Classification” drop down menu and then select the “OK” icon.

9. Follow the prompts to update the DCU to the latest software level using the Hino Diagnostic eXplorer II (Hino DX2). Refer to the following table for the appropriate software part number for the application.

DCU Software

PART NUMBER	MODEL YEAR
89550-37245	2018, 2019, 2020


10. Once DCU reprogramming is complete, turn the starter switch to the “LOCK” position and remove the key for one minute.




11. Insert the ignition key into the starter switch and turn the key to the “ON” position.



12. Again, select the “Reprogramming” icon.



13. Select “300 Series” under the “Vehicle Classification” drop down menu.



14. Select “ECU (Engine J-Series)” under the “System Classification” drop down menu and then select the “OK” icon.

15. Follow the prompts to update the ECU to the latest software level using the Hino Diagnostic eXplorer II (Hino DX2). Refer to the following table for the appropriate software part number for the application.

ECU Software

PART NUMBER	MODEL YEAR	ENGINE SERIES	QUANTITY
89663-E4046A	2018 Diesel	J05ETP	As Required By VIN
89663-E4056A	2018 Hybrid	J05EUG	
89663-E4644C	2019-2020 Diesel	J05ETP	As Required By VIN
89663-E4654C	2019-2020 Hybrid	J05EUG	


16. Once ECU reprogramming is complete, turn the starter switch to the “LOCK” position and remove the key for one minute.




17. Insert the ignition key into the starter switch and turn the key to the “ON” position.




18. During ECU software reprogramming, other DTC's may have been set. These DTC's will need to be cleared prior to completing this campaign. Select the "Diagnosis" icon.




19. Check mark the "Device Classification". This should automatically check mark the remaining devices. Select the "Read Out" icon.




20. Select the “Delete All” icon.




21. Select the “Delete” icon.




22. Select the “OK” icon.




23. From the Engine ECU Data Monitor and Active Test menu, select Active Test Setting>Urea SCR Related Memory Reset> then follow the prompts to complete the reset.



24. Select the “New Diagnosis” icon.



25. Select the “OK” icon.




26. Turn the starter switch to the “LOCK” position and remove the key.



REPAIR LABEL INSTALLATION PROCEDURE

Once all above steps in this recall procedure have been completed, apply a recall label to the left door jamb above the VIN label. Fill in the Campaign No, Dealer code, and Repair date. Proceed to the Final Inspection Procedure, below.



CALIFORNIA VEHICLES ONLY:

When an Emissions Recall is performed by a California Dealer a "Proof of Correction" certificate must be completed and provided to the vehicle owner to submit to the California Department of Motor Vehicles if requested during vehicle registration. If the "Proof of Correction" certificate is not provided, an owner may not be able to renew the vehicle registration. If not requested by the DMV, the form should be retained for the Owner's records. A downloadable form can be found on HinoNet/ Service/ Print Forms under the description "Proof of Correction".

Vehicle Emission Recall - Proof of Correction					
License Number	Make	Year Model	Body Type	Vehicle Identification Number	
				<input type="text"/>	
Manufacturer			Recall Number		
The above described vehicle has been repaired, modified and/or equipped with new emission control devices to meet applicable California Emission Control Laws.					
Dealer's		Address, City, State			
		Dealership's Authorized			
		☒			
Return this certificate to DMV <u>only</u> when required - otherwise retain for your records.					

FINAL INSPECTION:

- The Engine DCU and ECU module software were updated to the latest levels as outlined by this recall procedure.
- When reprogramming, DTC's may have inadvertently been set. Make certain that all codes logged as a result of the ECU reprogramming have been cleared from the Engine ECU, Transmission ECU, ABS ECU and DCU prior to releasing the truck back to the customer.
- The Urea SCR Related Memory Reset was performed.

CLAIM APPLICATION

COE DCU and ECU Reprogramming:

- a) Campaign No: AACR0
- b) Labor charge: 1.2 hrs.
- c) Warranty code: 86311
- d) Trouble code: 98
- e) Operation code: 86350AOT
- f) Original failed part: 9999999999

