

Service Bulletin

Bulletin No.: 19-NA-014

Date: January, 2019

TECHNICAL

Subject: False Trunk Ajar Message Displayed in Driver Information Center (DIC)

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Malibu	2019	2019			All	All

Involved Region or Country	North America and N.A. Export Regions		
Condition	Some customers may comment on an intermittent message shown on DIC stating; "Trunk Ajar." The trunk is actually not open in this condition.		
Cause	There may be an error present in the software that was not fixed by an Over-the-Air (OTA update. Either the OTA update failed or was declined by the customer.		
Correction	An OTA Update will occur remotely through in-vehicle prompts from the radio display. However, some customers may decline the vehicle update or the update may be unsuccessful. Customers will need the dealer to reprogram the <i>Serial Data Gateway Module</i> .		

Service Procedure

Note: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to www.gmdesolutions.com for further information. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

If the vehicle OTA Update fails or customer declines the vehicle update, refer to the *Serial Data Gateway Module Reprogramming* in SI.

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
9104164	Serial Data Gateway Module Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	Released January 25, 2019