

Service Bulletin

Bulletin No.: 19-NA-017

Date: February, 2019

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated - DTC P2096 and/or P2097

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Malibu	2017	2017			1.5L (LFV)	

Involved Region or Country	North America, Israel	
Condition	Some customers may comment that the MIL is illuminated. Some technicians may find one or more of the following DTCs set in the Engine Control Module (ECM): P2096: Post Catalyst Fuel Trim System Low Limit P2097: Post Catalyst Fuel Trim System High Limit	
Cause This condition may be caused by a software anomaly.		
Correction	If you encounter a vehicle with the above condition, reprogram the ECM with the latest available software.	

Service Procedure

Note: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to www.gmdesolutions.com for further information. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

Refer to K20 Engine Control Module: Programming and Setup in SI.

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time		
2886108*	Engine Control Module Reprogramming with SPS for P2096 and/or P2097	0.5 hr		
*This is a unique Labor Operation for Bulletin use only.				

Version	1
Modified	Released January 31, 2019