

## **Service Bulletin**

Bulletin No.: 17-NA-115

Date: February, 2019

## **TECHNICAL**

**Subject: Intermittent Vehicle Pulls While Driving** 

| Brand:    | Model: | Model Year: |      | VIN: |    | Engino  | Transmission: |
|-----------|--------|-------------|------|------|----|---------|---------------|
|           |        | from        | to   | from | to | Engine: | mansinission. |
| Chevrolet | Camaro | 2016        | 2017 |      |    |         |               |

| Involved Region or Country | North America and N.A. Export Regions  |  |  |
|----------------------------|--|--|--|
| Condition                  | Some customers may comment on an intermittent vehicle pull while driving. The pull may be either direction or it may also change directions in subsequent drive cycles.  Note: If a customer comments on a service power steering or Stabilitrak message, DO NOT follow this bulletin. Continue with diagnosis of steering concern according to published service information. |  |  |
| Cause                      | This condition may be caused by a software anomaly.  |  |  |
| Correction                 | An updated software calibration has been released to address this condition.  Important: DO NOT replace the steering gear for this condition.  |  |  |

## **Service Procedure**

**Note:** Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to <a href="https://www.gmdesolutions.com">www.gmdesolutions.com</a> for further information. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

Reprogram the power steering control module with the latest calibrations available on TIS2WEB. Refer to *Power Steering Control Module Programming and Setup* in SI.

## **Warranty Information**

| Labor<br>Operation | Description  | Labor Time                                     |
|--------------------|--|--|
| 2810625            | Power Steering Control<br>Module Reprogramming<br>with SPS | Use<br>Published<br>Labor<br>Operation<br>Time |

| Version  | 3  |
|----------|--|
| Modified | May 2, 2017 – Added the 2017 Model Year. February 08, 2019 – Added a Note to the Condition and updated the stable battery voltage during programming statement under Correction. |