

Service Bulletin

Bulletin No.: 17-NA-133

Date: February, 2019

TECHNICAL

Subject: No Propulsion, Malfunction Indicator Lamp, Battery Cut Off Indicator, and Shift to Park Messages, with DTC P0A5E, P0A61, P0A64, P0A67, P0A6A or P0A6D Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Branu.	woder.	from	to	from	to		
Cadillac	CT6 PLUG-IN	2017	2017			HP9	MRD

Involved Region or Country	North America			
Additional Options	Equipped with Electric Propulsion and Auto Electric Transmission (RPO HP9 and MRD)			
Condition	Some customers may comment on one or more of the following conditions: Loss of propulsion. Malfunction Indicator Lamp illuminated. Battery cut off lamp illuminated. Shift to park lamp illuminated. During diagnosis a technician may find one or more of the following DTCs set: P0A5E P0A61 P0A64 P0A67 P0A6A P0A6D			
Cause	This may be due to open welds or cold welds on the flex lead wires for the electric motors.			
Correction	Replace the transmission assembly.			

Service Procedure

If you encounter a vehicle with the above concern, replace the transmission assembly. Refer to *Transmission Replacement* in SI.

Version	2		
Modified	February 04, 2019 – Removed the Note referring the Technician to PIP5479 for diagnostics and ordering instructions prior to contacting TAC.		

