



A **PACCAR** COMPANY

Kenworth Truck Company  
Customer Service Department  
PO Box 1000  
Kirkland, Washington 98083-1000  
(425) 828-5888

Date TBD

[First VIN]  
Customer Name  
Address  
City, State Zip

Subject: TIB 34-064: T680/T880 Power Distribution Center (PDC) Replacement

Dear Kenworth Customer,

Your vehicle (listed within this letter) is eligible for a campaign to replace the Power Distribution Center (PDC). The PDC installed in your vehicle may have a fuse installed in a location that is not capable of supporting the amperage. The condition does not affect the safe operation of the vehicle but may result in DEF related fault codes.

Please contact a Kenworth dealership to schedule an appointment for this work. If you have already had this work performed, please disregard this letter. You can find your nearest Kenworth dealer at Dealer Locator on the website [www.Kenworth.com](http://www.Kenworth.com).

When contacting your selected Kenworth dealer, refer to campaign **TIB 34-064** and the VIN listed on this letter. The work will take approximately **1.0 hour**, depending on vehicle configuration and dealer scheduling. There will be no charge to you if completed within Standard Warranty (excludes Extended Warranty) or for upgrades completed by **02/01/2020**, whichever is greater. We apologize for this inconvenience but ask for your cooperation to ensure your continued satisfaction with Kenworth products.

If you require further information about this campaign, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact Kenworth Customer Service, provide your name, your dealer's city and state, your phone number, your email address (optional), the last 8 digits of your VIN, the bulletin number, and your question, using one of the following:

Email: [Kenworth.Campaigns@PACCAR.com](mailto:Kenworth.Campaigns@PACCAR.com) with the bulletin number in the subject line

or

Mail: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department

or

Phone: 425-828-5888

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

Thank you,

Shondip Chakravarty  
Director of Customer Service  
Kenworth Truck Company

VIN: [VIN List]



## Technical Information Bulletin

---

**34-064**



### Section

Wiring - 34

---

### Subject

T680/T880 Power Distribution Center (PDC) Replacement

---

### Release Date

1/24/2019

---

### Condition

Chassis that had fuse D7 Line Heat 2 replaced during the 2017 Emissions Retrofit [R1719](#) may have a PDC trace that is not capable of supporting the amperage.

---

### Chassis Affected

17 (all U.S. and no Canada) T680 and T880 chassis built from 06/01/2016 through 08/08/2016 included in the 2017 Emissions Quality Validation (QV) Retrofit program. See the attached chassis list.

---

### Action

CAMPAIGN

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. If you are not using Service Management to start repair orders, review DWWC or SIR for "Complete" next to the "34064" campaign code prior to performing this repair.
3. If this chassis also has 2017 Emissions Retrofit R1719 open in SIR, then complete R1719 and this bulletin at the same time.
4. Follow the procedures below to replace the PDC.

This campaign can be performed at any time convenient for the customer (for example: during the next scheduled maintenance interval).

## Warranty

Through Standard Warranty (excludes Extended Warranty) or for repairs completed by 02/01/2020, whichever is greater, Kenworth will pay for parts at dealer net plus applicable mark-up and labor:

- 0.5 hours labor to replace the PDC. File a long form claim.
- File an additional claim for extraordinary circumstances. A quick claim for standard labor must be filed first.

### Take-Off Parts Disposition: Destroy take-off parts

CLAIM CODING			
Failure Location:	034-004-008	Work Accomplished:	35
Failure Type:	700	Responsibility Code:	01
SRT Code:	034-xxx (0.5 hrs) replace PDC	Claim Type:	C

## Parts

Parts are available from PACCAR Parts.

### Label ordering procedure

**This procedure is for ordering the label only.** All other parts will be ordered through normal channels. Confirm with the customer that your dealership will be the repairing location before ordering parts and obtain the chassis number. **All orders** must be requested **through Support Link**. Please refer to the following instructions for how to submit a Support Link case:

The Support Link Case fields **must** be filled in as follows. Failure to do so **will** result in delays to the order processing.

1. **This procedure is for ordering the label only.** All other parts will be ordered through normal channels.
2. Open Support Link Case—**Special Orders** queue. In the Subject field enter "**34-064**".
3. Enter the part number that is needed based on the bulletin associated with the specific chassis number.
  - **If the part number is not provided in the case, the order will not be placed.** Only the label part number provided will be ordered thru this process.
4. Enter the chassis number in the designated field. **This is required for the order to be placed to validate participation in the campaign.**
5. Select a shipping method.
6. PPD will ship the requested part for the specific chassis:

**Contents:** Campaign parts per chassis (as provided in step #2)

**Shipping method:** as provided in step #4

**Delivery time:** depends on selected shipping method

**Packing slip will include:**

- Dealer Order Number as: "Campaign CH [ChassisNumber]"
  - Packing List (this may or may not match the Chassis\Parts List attached to this bulletin depending on availability of parts).
7. Ensure both the Parts and Service Managers are aware of the chassis specific order.

Ensure your dealership has all parts on hand before scheduling campaign work.

Quantity	Part Number	Description
1	P27-1234-01010	FUSE-ASSY CAB PDC 2.1M
1	S53-1373-021	Fuse block label kit

## **Procedure**

See the attached procedure.

## **Attachments**

 [Dealer\Chassis List](#)

 [Customer Letter](#)

 [PDC Replacement procedure](#)

Authored by: OF

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2019 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).