

Lack of A/C Performance at Idle in High Ambient Temperature

Service Category Vehicle Interior

Section Heating/Air Conditioning

Market USA

Toyota Supports
 ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2016 - 2019	Tacoma	VDS(s): AZ5CN, BZ5DN, CZ5AN, DZ5BN, EZ5CN, FZ5DN, GZ5AN, HZ5BN, RZ5CN, SZ5AN Engine(s): 2GR Transmission(s): 6AT

REVISION NOTICE

February 25, 2019 Rev1:

- Applicability has been updated to include 2019 model year Tacoma vehicles and engine and transmission types.
- The Warranty Information section has been updated.
- The Repair Procedure section has been updated with the addition of step 84.

Any previous printed versions of this bulletin should be discarded.

Introduction

Some 2016 – 2019 model year Tacoma vehicles may exhibit a condition where the air conditioning system shuts down and stops blowing cool air during periods of extended engine idle with ambient temperatures greater than 100°F. Follow the Repair Procedure in the bulletin to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
AC1901	Additional Cooling Kit	3.5	16410-0P290	7A	99

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Lack of A/C Performance at Idle in High Ambient Temperature

Parts Information

PART NUMBER	PART NAME	QTY
88590-35050	Blower Assy, W/Shroud	1
90080-87026	Relay	1
90119-A0078	Bolt, W/Washer	1
36869-04010	Cover, Packing	1
36869-04030		1
36869-04040		1
36867-04040	Seal, Packing	1
82112-04050	Wire, Engine Room No. 2	1
82662-0E080	Cover, Relay Block, Upr	1
82683-35220	Label, Fuse Block Notice	1
08231-00045	Silicone Tape	1
NAPA Auto Parts P/N: NW 737305 or Equivalent	¼ in. Diameter Corrugated Tubing	1
82715-35F50	Bracket, Wire Harness Clamp	1
90080-11180	Bolt, W/Washer	2
82999-12020	Terminal, Joint Repair	3
90464-00345	Clamp	32

NOTE

- Repair components are NOT available as a kit.
- ALL parts MUST be ordered separately.
- The quantity amounts listed above are for repairing one vehicle.

Lack of A/C Performance at Idle in High Ambient Temperature

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*	ADE	TS2UNIT	1
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

*Essential SST.

NOTE

- ONLY ONE of the Techstream units listed above is required.
- Software version 13.30.018 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

REQUIRED EQUIPMENT	PART NUMBER	QTY
Plastic Pry Tool Kit*	00002-06020-01	1
K Tool International 8-in-1 Quick and Easy Wire Stripper or Equivalent (Must Include INS Position)	KTI56207 Order Through www.walmart.com or Several Other Websites	1
Eclipse Tools CP-301G Pro'sKit Precision Wire Stripper, 30-20 AWG or Equivalent	CP-301G Order Through www.amazon.com	1

*Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

REQUIRED TOOLS & MATERIAL	PART NUMBER	QTY
Silicone Sealer (Form-in-Place Gasket – Oil Pan)	00295-00103	1
Wire Coat Hanger	–	1
Isopropyl Rubbing Alcohol	–	As Needed

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure

NOTE

This procedure includes the installation of an additional condenser cooling fan. The installation of these parts also requires the installation of an engine room sub-wire harness, passenger compartment harnesses, and an additional relay block.

1. Does the vehicle A/C system shut OFF while stopped, idling in Drive during high ambient temperature (100°F+)?

CAUTION

- Ensure the parking brake is firmly applied and hold your foot on the brake pedal.
- Conduct activity in an open area away from obstacles.


NOTE

This condition may NOT be possible to duplicate if ambient temperature is below 100°F.

- **YES** — Go to step 3.
 - **NO** — Continue to step 2.
2. If unable to duplicate the condition, confirm that the customer complaint is similar to the condition described in step 1.
Is the condition similar to the condition described in step 1?
 - **YES** — Continue to step 3.
 - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

3. Remove the radiator grille.
 - A. Disconnect the battery.
 - B. Apply protective tape around the radiator grille.
 - C. Remove the two screws holding the grille in place.
 - D. Using a clip remover, remove the two clips.
 - E. Disengage the 10 guides and remove the radiator grille.

Figure 1.




1	Clip
2	Screw
	Guide

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

4. Remove the left-hand radiator side deflector by removing the clip and disengaging the three claws.


Figure 2.



1	Clip
	Claw

5. Remove the right-hand radiator side deflector by removing the clip and disengaging the three claws.

Figure 3.



1	Clip – Two Outer Attachments
	Claw

Lack of A/C Performance at Idle in High Ambient Temperature


Repair Procedure (continued)

6. Modify the NEW condenser fan so there is no interference with the automatic transmission oil cooler mounting point.

Figure 4.



Figure 5.



1	Cut Condenser Fan Bracket
2	Automatic Transmission Cooler Mount

- A. Gently hold the base mount of the condenser fan in a vise.

Figure 6.



1	Side Bracket
----------	---------------------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- B. Using an abrasive cutting wheel or similar cutting tool, cut off the right side mount.


Figure 7.



1	Trim Here
----------	------------------

- C. Measure 25 mm from the top of the mount and cut off the remaining portion.

Figure 8.



1	25 mm
----------	--------------

- D. Clean off ALL remaining plastic burrs from the cut surface.

Figure 9. Finished Mount Modification




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

7. Install the NEW condenser fan.
 - A. Slide the two bottom mounts of the condenser fan over the sheet metal lip of the radiator core support.
 - B. Install the bolt into the top mount.

Figure 10.



1	Bolt
2	Bottom Mount

8. Locate the bolt holes on the driver side inner fender. Attach the NEW bracket to the inner fender with the bolts provided in the kit.

Torque: 9.8 – 18.1 N*m
(100 – 185 kgf*cm, 7.5 – 13ft*lbf)

Figure 11.



Figure 12.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

9. Install the NEW notice label on the inside of the NEW relay block relay cover.

Figure 13.



10. Install the NEW relay into the “CDS FAN” location as indicated on the notice label.

Figure 14.



11. Attach the relay block to the bracket installed in step 8.

Figure 15.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


12. Remove the left-hand and right-hand front door scuff plates by disengaging the 10 claws and two guides.

Figure 16.



13. Remove the left-hand and right-hand cowl side trim board.
 - A. Remove the clip.

Figure 17.




- B. Disengage the two clips and guide to remove the cowl side trim board.

HINT

Repeat the same removal process for the right-hand side.

Figure 18.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


14. Disconnect the hood lock control lever sub-assembly by disengaging the claw and three guides.

Figure 19.



15. Remove the instrument panel lower finish panel sub-assembly.
 - A. Remove the bolt.
 - B. Remove the two screws.
 - C. Disengage the 11 clips and four claws.
 - D. Disconnect the connectors and remove the instrument panel lower finish panel sub-assembly.

Figure 20.




1	Bolt
2	Screw
	Clip
	Claw

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


16. Remove the right-hand instrument side panel by disengaging the four claws, three clips, and three guides.

Figure 21.



17. Remove the glove box compartment plate by disengaging the five clips.

Figure 22.




18. Remove the lower No. 2 instrument panel airbag assembly.

CAUTION

- Wait **AT LEAST 90 seconds AFTER** the ignition switch is turned to the **LOCK** position and the negative (-) terminal cable is disconnected from the battery.
- The SRS is equipped with a backup power source, so if work is started within 90 seconds **AFTER** disconnecting the negative (-) terminal cable of the battery, the SRS may be deployed.

- A. Remove the three bolts.
- B. Use a screwdriver with its tip wrapped in protective tape to release the airbag protector lock.

Figure 23.



1 Protective Tape

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


- C. Disconnect the airbag connector and remove the No. 2 instrument panel airbag assembly.

NOTICE

When handling the airbag connector, take care not to damage the wire harness.


19. Remove the instrument lower panel assembly by removing the five screws.

Figure 24.



20. Remove the passenger side foot air duct by removing the screw.

Figure 25.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


21. Route the battery+ and pusher fan sub-wire harnesses from the relay block attached in step 11 through the engine compartment.

Figure 26.



1	Engine Room Sub-wire Harness
2	Pusher Fan Sub-wire Harness
3	Battery+ Sub-wire Harness
4	Relay Block
5	A/C ECU Pigtail and Driver J/B Sub-wire Harness
6	A/C ECU Sub-wire Harness
7	Passenger Compartment Sub-wire Harness

Figure 27.



A	A/C ECU
B	Passenger Compartment
C	Evaporator Case
D	Engine Compartment
E	A/C ECU Sub-wire Harness

F	Driver J/B
G	Driver J/B Sub-wire Harness
H	Grommet
I	Brake Booster
J	A/C ECU Pigtail
K	TSB-Added Relay Block
L	Engine Room Relay Block
M	Battery (+) Sub-wire Harness
N	Battery
O	Pusher Fan Sub-wire Harness
P	Radiator
Q	TSB Pusher Fan
R	Front
S	Driver Side
T	Rear
U	Passenger Side

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- A. Remove the bolt from the engine room relay block bracket and route the NEW sub-wire harness behind the bracket.
- B. Loop and bring the NEW A/C ECU pigtail and driver J/B sub-wire harnesses back behind the bracket, which will later be routed into the passenger compartment.
- C. Apply a tie band at the marked location on the sub-wire harness, attach it to the engine room relay block bracket, and cut off the excess.

Figure 28.



1	A/C ECU Pigtail & Driver J/B Sub-wire Harnesses
2	Engine Room Relay Block Bracket Bolt

- D. Reinstall the engine room relay block bracket bolt.

Figure 29.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- E. Route the battery+ sub-wire harness between the engine room relay block and the battery.

Figure 30.



1	Vehicle Battery+ Cable
2	Battery+ Sub-wire Harness

- F. Unscrew the nut from the stud bolt on the positive battery cable.
- G. Put the ring terminal from the NEW sub-wire harness (white) onto the stud bolt flange side up.
- H. Tighten the nut.
Torque: 9.8 – 15.7 N*m
(103 – 159 kgf*cm, 7.5 – 11.5 ft*lbf)

Figure 31.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- I. Apply tie bands at the marked locations on the NEW sub-wire harness, attach it to the bottom side of the negative (-) battery cable between the engine room relay block and the battery, and cut off the excess.

Figure 32.




1	Tie Bands
2	Negative (-) Battery Cable

- J. Remove the ground terminal from the engine room harness.
 - (1) Attach the ring terminal from the NEW sub-wire harness white wire.
 - (2) Reinstall the ground terminal into the original position.

Torque: 7 – 9.8 N*m
(71 – 100 kgf*cm, 5 – 7.2 ft*lbf)

Figure 33.




1	Engine Room Harness Ground Terminal
2	Sub-wire Harness Ground Ring Terminal

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


- K. Continue to route the pusher fan sub-wire harness forward along the side of the battery and up the side of the radiator, attach it to the engine room harness at the marked locations with tie bands, and cut off the excess.

Figure 34. Battery



1	Tie Bands
----------	------------------

Figure 35. Radiator




1	Tie Bands
----------	------------------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


- L. Remove the radiator support frame seal by removing the seven clips and the frame seal.

Figure 36.



- M. Continue to route the pusher fan sub-wire harness over the top driver side of the radiator, attach it to the engine room harness at the marked locations with tie bands, and cut off the excess.

Figure 37. Radiator (Driver Side)




1	Tie Bands
----------	------------------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- N. Route the pusher fan sub-wire harness through the top front of the radiator.
- O. Attach the pusher fan sub-wire harness to the bottom of the hood latch with a tie band and cut off the excess.
- P. Connect the sub-wire harness pusher fan connector to the NEW pusher fan included.

Figure 38.



1	Tie Band
2	Sub-wire Harness Pusher Fan Connector

- 22. The A/C ECU pigtail and driver J/B sub-wire harnesses from the engine compartment will be routed into the passenger compartment through the engine compartment bulk head grommet located next to the power brake booster.

Figure 39.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

23. The A/C ECU pigtail and driver J/B sub-wire harnesses will be routed into the passenger compartment through the bottom of the grommet that will require modification.

Figure 40.



1	Sub-wire Harness Grommet Passage
----------	---

24. Modify the bulk head grommet by using scissors or equivalent and cut off the rubber end of the passage at the indent mark to expose the passage through to the passenger compartment.

Figure 41.



1	Grommet Indent Mark
----------	----------------------------

Figure 42.



1	Cut at Grommet Indent Mark
2	Modified Grommet


Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

25. Confirm the orientation of the grommet passage is between the 6 and 8 o'clock positions, viewing it from the engine compartment side.


If the grommet is NOT in this orientation, rotate the bulk head grommet so the passage is in the proper orientation.

Figure 43.



26. Using the diagonal cutters, remove and discard the connector end from the A/C ECU pigtail sub-wire harnesses BEFORE routing it through the engine compartment grommet.

Figure 44.




1	Cut Connector End Off
----------	------------------------------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

27. Remove the vinyl tube protecting the pin on the end of the driver J/B sub-wire harness by removing the black tape and vinyl tube exposing the pin.

Figure 45.




28. Cut the bottom straight portion of a wire coat hanger approximately 30 cm in length and bend one end of it backward onto itself.

Figure 46.



29. Place the ends of the driver J/B sub-wire harness and A/C ECU pigtail into the bent end of the coat hanger wire.

Figure 47.



30. Using silicone tape, measure a 40 mm length, cut with scissors, and snugly wrap the bent end of the wire coat hanger and two wire ends with the silicon tape.

Figure 48.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

31. Using scissors, cut the corner of a used parts bag enough to cover the end of the bent wire coat hanger and wire ends.

Figure 49.



32. Wrap the bent end of the wire coat hanger with the cut corner of the plastic parts bag and dip the end in isopropyl rubbing alcohol.

Figure 50.



HINT

This step aides in passing the wire coat hanger and the attached wires through the rubber grommet passage.

33. From the engine compartment side, gently insert the bent end of the wire coat hanger through the bulk head grommet passage previously made in step 24.

Figure 51.



HINT

The wire coat hanger assists sending the wires through the passage to the passenger compartment side of the grommet.

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

34. Insert the bent wire coat hanger all the way through into the passenger side so the plastic is free of the grommet.

Figure 52.



35. Gently remove the plastic and the silicone tape, taking care to not damage the wire ends, and free the wires from the wire coat hanger. Gently pull the remaining length of the wire coat hanger through the passage and discard.
36. From the passenger compartment, pull the A/C ECU pigtail and driver J/B sub-wire harnesses through the grommet until the corrugated wire harness covers meet up against the grommet on the engine compartment side.

Figure 53.



1	Passenger Compartment – Sub-wire Harnesses Pulled Through Grommet
----------	--

Figure 54.



1	Engine Compartment – Corrugated Sub-wire Harness Covers
----------	--

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

37. From the engine compartment, route the A/C ECU pigtail and driver J/B sub-wire harnesses along the engine room harness, attach with tie bands, and cut off the excess.

Figure 55.




1	A/C ECU Pigtail and Driver J/B Sub-wire Harnesses
----------	--

38. Once the A/C ECU pigtail and driver J/B sub-wire harnesses are properly placed in the passenger compartment, install the ¼ in.-diameter corrugated tubing to both sub-wire harnesses.

NOTE

- The ¼ in.-diameter corrugated tubing is NOT included. It can be sourced through NAPA Auto Parts P/N: NW 737305 or equivalent.
- Corrugated tube length for A/C ECU pigtail sub-wire harness = Maximum of ~160 mm or less.
- Corrugated tube length for driver J/B sub-wire harness = Maximum of ~560 mm or less.

Figure 56.




1	A/C ECU Pigtail Sub-wire Harness
2	Driver J/B Sub-wire Harness

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- A. Slide the corrugated tube over the A/C ECU pigtail sub-wire harness so the wire protrudes 60 mm from the corrugated tube.

Figure 57.



1	60 mm
2	Corrugated Tube

- B. Wrap the entire length of the corrugated tube with electrical tape. Begin at the section of wire protruding closest to the end of the corrugated tube as shown.


Figure 58.



Figure 59.



Figure 60.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- C. Slide the corrugated tube over the driver J/B sub-wire harness so the wire protrudes 60 mm from the corrugated tube.

Figure 61.



1	60 mm
2	Corrugated Tube

- D. Wrap the entire length of the corrugated tube with electrical tape as shown.

Figure 62.



Figure 63.



Figure 64.



Lack of A/C Performance at Idle in High Ambient Temperature


Repair Procedure (continued)

39. In the driver side J/B, locate connector 1F (32 pin), pull open the connector lock lever, and remove the connector.

NOTE

Connector 1F applies to both manual and automatic air conditioning systems.

Figure 65.



40. Remove the black, plastic lock lever from the connector.

Figure 66.




Figure 67.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

41. Remove the electrical tape from the connector harness and pull back the wire harness cover to expose the wires.

Figure 68.



NOTICE

- The connection of the NEW driver J/B sub-wire harness to the driver side J/B 1F connector will depend on whether there is a pin in pin location 16 of the 1F connector.
- For both manual and automatic A/C, the connection at the driver J/B will be made at pin location 16 of connector 1F.

Is there a pin and wire in pin location 16 of the 1F connector?

- **YES** — Continue to step 42 for the wire splice connection procedure.
- **NO** — Go to step 43 for the pin insertion procedure.

Figure 69.






Figure 70.



42. Confirm there is a pin and wire in pin location 16 in connector 1F. The connection will be made with a wire splice procedure.
 - A. From the back side of connector 1F, locate and isolate the pin 16 wire.
 - B. Measure 60 mm along the pin 16 wire from the base of connector 1F and mark the wire.
 - C. Using the diagonal cutters, cut the pin 16 wire at the 60 mm mark.

Figure 71.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- D. Using the wire stripper (P/N CP-301G; use 24 AWG/0.5 mm to strip insulation from wire), strip 11 mm of the wire insulation from the end of pin16 wire.

CAUTION

- Due to the small gauge of the pin 16 wire, be very careful NOT to cut off ANY strands of the wire while stripping the wire insulation, or the integrity of the wire will be compromised.
- If strands of wire are cut off during the wire stripping process, cut off the stripped wire and repeat the process. Be careful not to cut the wire too short, or the splice process will be difficult.

Figure 72.



Figure 73.



- E. Locate the NEW driver J/B sub-wire harness and using the diagonal cutters, cut off and discard the pin at the end of the harness.
- F. Using the wire stripper, strip 11 mm of wire insulation from the end of the wire.

CAUTION

- Be very careful NOT to cut off ANY strands of the wire while stripping the wire insulation, or the integrity of the wire will be compromised.
- If strands of wire are cut off during the wire stripping process, cut off the stripped wire and repeat the process. Be careful not to cut the wire too short, or the splice process will be difficult.

Figure 74.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- G. Join the stripped end of the NEW driver J/B sub-wire harness to the stripped end of the pin 16 wire in connector 1F.

Figure 75.




- H. Twist the two stripped wire ends together uniformly.

CAUTION


Due to the wire gauge size differences between the two wires, ensure the wire ends twist around each other evenly.

Figure 76.



1 Wires Twisted Together Uniformly – Good

Figure 77.




1 Thin Wire Twisted Around Thick Wire – Not Good

- I. Slide the NEW blue joint terminal over the twisted wire ends so the stripped portion of the wires are positioned in the middle of the joint terminal pressure contact section.

CAUTION

Be very careful not to bend ANY of the stripped wire strands backward as the terminal joint slides over the stripped wire ends.

Figure 78.



1 Blue Joint Terminal

2 Pressure Contact Section


Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

NOTE

For the following steps when the wire crimp tool is required, use a crimp tool that includes insulated terminal crimp features and INS.


Figure 79.



1	Insulated Terminal Crimp (Blue)
2	INS Crimp


J. Using a wire crimp tool, place the joint terminal into the blue dot position of the crimp jaws and center the terminal.

Figure 80.



K. Squeeze the crimp tool until the ends of the crimp tool come in contact with each other, ensuring a good quality crimp.

Figure 81.



1	Close Here
---	------------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- L. While holding the joint terminal, gently tug on the wires to ensure the crimp is good.

NOTICE

If the wires pull out of the joint terminal or the crimp fails, replace the joint terminal with a NEW one and then crimp again.

- M. Crimp both ends of the joint terminal with the crimp tool at the INS position.

Figure 82.



- N. Using silicone tape, measure a 150-mm length piece of tape and cut it with scissors.

NOTICE

Do NOT let the silicone tape fold or touch itself as it is very difficult to unstick once this has occurred.

Figure 83.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- O. Wrap the joint terminal with the silicone tape by placing the tape lengthwise along the terminal so the end of the tape hangs below the terminal, approximately the width of the tape.

NOTICE

During the wrapping process of the joint terminal with the silicone tape, keep the silicone tape in tension (stretched) at ALL times.

Figure 84.



- P. Fold the silicone tape over the top of the joint terminal and down the opposite side of the terminal, adhering the tape to itself over the terminal area.

Figure 85.



- Q. Continue to wrap the terminal from the bottom up to the top of the terminal, and ensure the tape is adhered to itself.

Figure 86.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- R. Fold the wire back onto itself from the opposite end of the pin 16 wire, which remains, and using electrical tape, tape the wire back into the harness.

Figure 87.



Figure 88.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- S. Place the splice connection along the wire harness, fold back the driver J/B sub-wire harness along the connector harness, and completely wrap with electrical tape.

Figure 89.




Figure 90.




Figure 91.




- T. Go to step 44.

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


43. Confirm that there is no pin or wire in cavity location 16 in connector 1F. The connection will be made with a pin insertion procedure.

Figure 92.



- A. Using a small screwdriver, raise the pin lock retainer from connector 1F.

Figure 93.




- B. Locate the NEW driver J/B sub-wire harness and insert the pin from the end of the harness into cavity location 16 in connector 1F until the pin locks into the cavity and cannot be pulled out.

CAUTION

BEFORE inserting the pin into the connector, ensure the pin locking feature is facing the side of the connector with the pin lock retainer.

Figure 94.



1	Pin Locking Feature
2	Connector Pin Lock Retainer

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- C. Close the pin lock retainer at the top of connector 1F.
 - D. Hold the driver J/B sub-wire harness along the driver side J/B harness and completely wrap the wire harnesses together with electrical tape (similar to the procedure in step 42, substep S).
44. Reapply the driver side J/B wire harness cover previously pulled back in step 41 and completely wrap with electrical tape.

Figure 95.



Figure 96.



Figure 97.



45. Reinstall the black plastic lock lever to connector 1F.
46. Reconnect connector 1F to the driver side J/B.

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

47. Locate the NEW A/C ECU pigtail and slide the NEW joint terminal over the end of the wire.

Figure 98.



1	A/C ECU Pigtail
---	-----------------

48. Using the wire stripper, strip 11 mm of wire insulation from the end of the A/C ECU pigtail wire.

CAUTION

- Be very careful not to cut off ANY strands of the wire while stripping the wire insulation, or the integrity of the wire will be compromised.
- If strands of wire are cut off during the wire stripping process, cut off the stripped wire and repeat the process. Be careful not to cut the wire too short, or the splice process will be difficult.

Figure 99.





Figure 100.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

49. Locate the NEW A/C ECU sub-wire harness, and using the diagonal cutters, cut the plastic connector off and discard the connector.

Figure 101.



1

Cut Connector End Off From the A/C ECU Sub-harness

50. Using the wire stripper, strip 11 mm of wire insulation from the end of the A/C ECU sub-wire harness where the plastic connector was previously cut off in step 49.

CAUTION

- Be very careful not to cut off ANY strands of the wire while stripping the wire insulation, or the integrity of the wire will be compromised.
- If strands of wire are cut off during the wire stripping process, cut off the stripped wire and repeat the process. Be careful not to cut the wire too short, or the splice process will be difficult.

Figure 102.



51. Overlap the two stripped wire ends from the NEW A/C ECU pigtail and the NEW A/C ECU sub-wire harness.

Figure 103.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- Slide the NEW blue joint terminal over the stripped portion of the wires so that they are positioned in the middle of the joint terminal pressure contact section.

CAUTION

Be very careful not to bend ANY of the stripped wire strands backward as the terminal joint slides over the stripped wire ends.

Figure 104.





Figure 105.




1	Blue Joint Terminal
2	Stripped Wires
3	Pressure Contact Section

NOTE

For the following steps when using the wire crimp tool is required, use a crimp tool that includes insulated terminal crimp features and INS.

Figure 106.



1	Insulated Terminal Crimp (Blue)
2	INS Crimp

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


53. Using a crimp tool, place the joint terminal into the blue dot position of the crimp jaws and center the terminal.

Figure 107.



54. Squeeze the crimp tool until the ends of the crimp tool come in contact with each other, ensuring a good-quality crimp.

Figure 108.




1	Close Here
----------	-------------------

55. While holding the joint terminal, gently tug on the wires to ensure the crimp is good.

NOTICE
 If the wires pull out of the joint terminal or the crimp fails, replace the joint terminal with a **NEW** one and then crimp again.

Figure 109.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

56. Crimp both ends of the joint terminal with the crimp tool at the INS position.

Figure 110.



57. Using silicone tape, measure a 150-mm length piece of tape and cut it with scissors.

Figure 111.




NOTICE

Do NOT let the silicone tape fold or touch itself as it is very difficult to unstick once this has occurred.

58. Wrap the joint terminal with the silicone tape by placing the tape about 10 mm from the end of the joint terminal on the wire and wrap the wire three or more times, keeping the silicone tape in tension.

Figure 112.



1	10 mm
---	-------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

59. Continue to wrap the tape around the joint terminal, ensuring good adhesion until the terminal is completely wrapped.

Figure 113.



Figure 114.




60. Repeat the same joint terminal wrapping process as used in steps 57 – 59, using electrical tape.

Figure 115.



61. At the splice location on the NEW A/C ECU sub-wire harness, gently fold the A/C ECU sub-wire harness onto itself, join it with the NEW driver J/B sub-wire harness, wire-tie both harnesses to the I/P harness, and cut off the excess from the tie band.

Figure 116.




1	Tie Band
----------	-----------------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

62. Continue to route the A/C ECU sub-wire harness up the I/P harness, attaching it with a tie band and cutting off the excess.

Figure 117.



1	Tie Band
---	----------

63. Continue to route the A/C ECU sub-wire harness over the pedal cluster assembly and steering column, and attach it to the I/P harness with a tie band and cut off the excess.

CAUTION
 Make sure the **NEW** harness does **NOT** interfere with the steering shaft or **ANY** other moving parts in this location.

Figure 118.




1	Tie Band
---	----------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


64. Wire-tie the NEW A/C ECU sub-wire harness to the HVAC harness and cut off the excess.
65. Route the A/C ECU sub-harness over the heater core pipes, providing enough slack in the harness to avoid contacting the pipes.
66. Route the A/C ECU sub-wire harness along the outside of the evaporator case and wire-tie the harness to the evaporator case loop hole.
67. Route the NEW A/C ECU sub-wire harness under the evaporator case through to the passenger compartment foot well area, wire-tie the harness to the HVAC harness, and cut off the excess.

Figure 119.



1	Tie Bands
2	Evaporator Case Loop Hole

Figure 120.




1	Tie Band
----------	-----------------

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


68. The connection of the NEW A/C ECU sub-wire harness to the A/C ECU connector will depend on whether the vehicle has manual or automatic A/C.

Figure 121.



- A. Manual A/C vehicles will ONLY have one connector (A14) at the A/C ECU.
- (1) If connector A14, pin 16 has a pin/wire, the connection of the NEW A/C ECU sub-wire harness to connector A14 will be made by a wire splice process.
 - (2) If connector A14, pin 16 does NOT have a pin/wire, the connection of the NEW A/C ECU sub-wire harness to connector A14 will be made by a pin insertion process.

Figure 122. Manual A/C Connect A14




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- B. Automatic A/C vehicles will have two connectors to the A/C ECU. The connection of the A/C ECU sub-wire harness to the A/C ECU will be made through connector A35.
- (1) If connector A35, pin 8 has a pin/wire, the connection of the NEW A/C ECU sub-wire harness to connector A35 will be made by a wire splice process.
 - (2) If connector A35, pin 8 does NOT have a pin/wire, the connection of the NEW A/C ECU sub-wire harness to connector A35 will be made by a pin insertion process.

Figure 123. Automatic A/C Connect A35




NOTICE

The following wire splice and pin insertion process of the A/C ECU sub-wire harness to the A/C ECU connector is shown for an automatic A/C at connector A35. However, the process is the same for manual A/C at connector A14.

69. At the A/C ECU, disconnect the A35 connector (A14 connector for manual A/C).

Figure 124.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

70. Remove the electrical tape from the connector harness to expose the wires.

Figure 125.



Figure 126.



NOTICE

The connection of the NEW A/C ECU sub-wire harness to the A/C ECU A35 connector will depend on whether there is a pin in pin location 8 of the A35 connector (or pin location 16 in connector A14 for manual A/C).

Is there a pin and wire in pin location 8 in connector A35 (or pin location 16 in connector A14 for manual A/C)?

- **YES** — Continue to step 71 for the wire splice connection procedure.
- **NO** — Go to step 72 for the pin insertion procedure.

71. Confirm that there is a pin and wire in pin location 8 in connector A35 (or pin location 16 in connector A14 for manual A/C).

- A. From the back side of connector A35, locate and isolate pin 8 wire (pin 16 in connector A14 for manual A/C).
- B. Measure 60 mm along the pin 8 wire from the base of connector A35 and mark the wire.

Figure 127.



- C. Using the diagonal cutters, cut the pin 8 wire (pin 16 wire for manual A/C) at the 60 mm mark.

Figure 128.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- D. Using the wire stripper (P/N CP-301G; use 24 AWG/0.5 mm to strip insulation from wire), strip 11 mm of wire insulation from the end of the pin 8 wire (pin 16 wire for manual A/C).


CAUTION

- Due to the small gauge of pin wire, be very careful not to cut off ANY strands of the wire while stripping the wire insulation, or the integrity of the wire will be compromised.
- If strands of wire are cut off during the wire stripping process, cut off the stripped wire and repeat the process. Be careful not to cut the wire too short, or the splice process will be difficult.

- E. Locate the NEW A/C ECU sub-wire harness, and using the diagonal cutters, cut off and discard the pin at the end of the harness.

- F. Using the wire stripper, strip 11 mm of the wire insulation from the NEW A/C ECU sub-wire harness.

Figure 129.



CAUTION

- Be very careful not to cut off ANY strands of the wire while stripping the wire insulation, or the integrity of the wire will be compromised.
- If strands of wire are cut off during the wire stripping process, cut off the stripped wire and repeat the process. Be careful not to cut the wire too short, or the splice process will be difficult.

- G. Join the stripped end of the NEW A/C ECU sub-wire to the stripped end of the pin 8 wire in connector in A35 (pin 16 wire in connector A14 for manual A/C).

Figure 130.



Lack of A/C Performance at Idle in High Ambient Temperature


Repair Procedure (continued)

- H. Twist the two stripped ends together uniformly.

CAUTION


Due to the wire gauge size differences between the two wires, ensure the wire ends twist around each other evenly.

Figure 131.



1	Wires Twisted Together Uniformly – Good
---	---

Figure 132.




1	Thin Wire Twisted Around Thick Wire – No Good
---	---

- I. Slide the NEW blue joint terminal over the twisted wire ends so that the stripped portion of the wires are positioned in the middle of the joint terminal pressure contact section.

CAUTION

Be very careful not to bend ANY of the stripped wire strands backward as the terminal joint slides over the stripped wire ends.

Figure 133.



1	Blue Joint Terminal
2	Pressure Contact Section


Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

NOTE

For the following steps when the wire crimp tool is required, use a crimp tool that includes insulated terminal crimp features and INS.


Figure 134.



1	Insulated Terminal Crimp (Blue)
2	INS Crimp

- J. Using a wire crimp tool, place the joint terminal into the blue dot position of the crimp jaws and center the terminal.

Figure 135.



- K. Crimp both ends of the joint terminal with the crimp tool at the INS position.

Figure 136.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- L. Using silicone tape, measure a 150 mm length piece of tape and cut it with scissors.

NOTICE

Do NOT let the silicone tape fold or touch itself as it is very difficult to unstick once this has occurred.

Figure 137.



- M. Begin wrapping the NEW joint terminal with silicone tape by placing the tape lengthwise along the terminal so that the end of the tape hangs below the terminal, approximately the width of the tape.

NOTICE

During the wrapping process of the joint terminal with the silicone tape, keep the silicone tape in tension (stretched) at ALL times.

Figure 138.



- N. Fold the silicone tape over the top of the joint terminal and down the opposite side of the terminal, adhering the tape to itself over the terminal area.

Figure 139.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- O. Continue wrapping the terminal from the bottom to the top of the terminal, ensuring the tape is adhered to itself.

- P. Fold the wire back onto itself from the opposite end of the pin 8 wire (pin 16 wire for manual A/C) which remains, and using electrical tape, tape the wire back into the harness.

Figure 140.






Figure 141.



1	Remaining Pin 8 Wire to Harness to Fold Back
----------	--

Figure 142.



1	Remaining Electrical Tape (Pin 8 Wire to Harness)
----------	---

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- Q. Place the splice connection along the wire harness and fold back the A/C ECU sub-wire harness along the connector harness and begin wrapping with electrical tape until it is completely wrapped.

Figure 143.





Figure 144.




Figure 145.



- R. Go to step 73.

- 72. Confirm there is no pin or wire in cavity location 8 in connector A35 (or pin location 16 in connector A14 for manual A/C).

Figure 146.




Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)


- A. Using a small screwdriver, raise the pin lock retainer from connector A35.

Figure 147.



- B. Locate the NEW A/C ECU sub-wire harness and insert the pin from the end of the harness into cavity location 8 in connector A35 (cavity 16 in connector A14 for manual A/C) until the pin locks into the cavity and cannot be pulled out.

Figure 148.



CAUTION

BEFORE inserting the pin into the connector, ensure the pin locking feature is facing the side of the connector with the pin lock retainer.

1	Connector Pin Lock Retainer
2	Pin Locking Feature


- C. Close the pin lock retainer at the top of connector A35.
- D. Reconnect connector A35 to the A/C ECU (connector A14 for manual A/C).

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

73. Take the excess length of the NEW A/C ECU sub-harness, loop it up and back down alongside the blower motor case, wire-tie it to the harness, and cut off the excess.


Figure 149.



1	Tie Bands
----------	------------------

74. At the front of the radiator core support, install the three NEW radiator core support body plugs and the skid plate seal.

Figure 150.



1	Upper Left-Hand Body Plug
2	Lower Left-Hand Body Plug
3	Right-Hand Body Plug
4	Skid Plate Seal

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- A. Install the two NEW left-hand body plugs in the indicated locations on the left side of the radiator core support.

Some vehicles may require modification to the upper left-hand body plug to allow clearance for the metal tab.

Figure 151.






Figure 152.



1	Metal Tab
2	Metal Tab Clearance Modification

Figure 153.



1	Upper Left-Hand Body Plug
2	Lower Left-Hand Body Plug

Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- B. Install the NEW right-hand body plug in the indicated locations on the right side of the radiator core support.

Figure 154.






Figure 155.



1	Right-Hand Body Plug
----------	-----------------------------

- C. Remove the No. 1 engine under cover sub-assembly by removing the four bolts.

Figure 156.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

- D. Install the NEW skid plate seal in the position as shown.

Figure 157.




- E. Reinstall the No. 1 engine under cover sub-assembly with the four bolts.

Torque: 30 N*m (306 kgf*cm, 22 ft*lbf)


- 75. Reinstall the passenger side foot air duct removed in step 20.

Figure 158.



- 76. Reinstall the instrument lower panel assembly removed in step 19.

Figure 159.



Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

77. Reinstall the lower No. 2 instrument panel airbag assembly.

A. Connect the airbag connector.

NOTICE


When handling the airbag connector, take care not to damage the wire harness.

B. Push in the airbag connector lock to install the airbag connector.

C. Install the lower No. 2 instrument panel assembly with the three bolts.

Torque: 10 N*m (102 kgf*cm, 7 ft*lbf)

Figure 160.



78. Reconnect the negative (–) battery terminal.

Torque: 5.4 N*m (55 kgf*cm, 48 in*lbf)

79. Start the vehicle, turn the air conditioner ON, and set the blower speed and temperature to the lowest setting.

80. Confirm the NEW pusher fan operation by gently sliding a piece of cardboard between the condenser and radiator to block the airflow, then check that the pusher fan turns ON within 2 minutes.

CAUTION

Be careful that the engine does not overheat during the fan operation confirmation process.

- A. Once proper pusher fan operation is confirmed, turn OFF the ignition and gently remove the cardboard from between the condenser and radiator, then continue reassembly of previously removed parts.
- B. If the pusher fan does NOT turn on, turn OFF the ignition and gently pull out the cardboard from between the condenser and radiator.
- C. Confirm proper installation of pusher fan components.
 - Confirm ALL connectors are fully connected and seated.
 - Confirm ALL ground points are properly connected and secured.
 - Confirm circuit integrity through ALL splice points.


Lack of A/C Performance at Idle in High Ambient Temperature

Repair Procedure (continued)

81. Reinstall ALL previously removed interior trim panels, air deflectors, frame seal, and grille.

82. Seal the wire harness passage end to prevent water entry.
 Dab silicone sealer on the end of your finger and apply it to the wire harness passage end on the engine compartment side of the bulk head grommet.

Figure 161.



1	Silicone Sealer Application
----------	------------------------------------

83. Verify installation and air conditioning operation.

84. Perform the millimeter wave radar sensor adjustment.

NOTE
 For vehicles equipped with Toyota Safety System.

Refer to TIS, applicable model and model year Repair Manual:

- 2018 – 2019 Tacoma:
 Engine/Hybrid System – Cruise Control – [“Cruise Control: Millimeter Wave Radar Sensor: Adjustment”](#)