



# Technical Service Bulletin

---

## PSS 01 D5 A8 3.0TFSI Bank 1 engine misfires

01 19 08 2054113/1 March 5, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2019	All	3.0TFSI

## Condition

This PSS only applies if all of the following conditions are met, see Figure 1 for an example:

- MIL on, MIL flashing, or misfires reported by customer.
- Misfire DTCs are stored for more than one cylinder on Bank 1.
- DTC ambient conditions show misfires occurring at or near same time stamp.
- DTC ambient conditions show misfires occur while engine operating condition is “Leerlauf” (idle in German).
- DTC ambient conditions show misfires occur when vehicle is at or near 0 km/h speed.
- Vehicle is NOT currently misfiring when examined in workshop.

If all of the above criteria are not met, this PSS does not apply and vehicle should be diagnosed using the normal GFF process.



# Technical Service Bulletin

---

<b>DTC memory entry</b>		
Number:	P030100: Cyl.1 Misfire Detected	
Error type 2:	passive/sporadic	
Symptom:	10591	
Status:	00100000	
<b>Standard ambient conditions:</b>		
Date:	11/16/18	
Time:	12:12:21 PM	
Mileage (DTC):	96	
Priority:	2	
Frequency counter:	1	
Elimination counter / driving cycle:	255	
<b>Expanded ambient conditions:</b>		
Engine speed	603.0	1/min
Normed load value	24.705883	%
Vehicle speed	0	km/h
Coolant temperature	77	°C
Intake air temperature	34	°C
Ambient air pressure	1010	mbar
Voltage terminal 30	14.24	V
Dynamic environmental data		
20 96 28 10 7A 03 11 BD 0C 7B 3E FC		
05 12 16 08 47 15 14 04 1B 60 00 30 10		
10 04 9E		
Unlearning counter according OBD		
40		
Engine status		
COENG_RUNNING		
Param_TestProgrCoEngStCOMPUVERBUBYTE		
3		
Engine oil temperature		
46.36 °C		
Engine operating condition		
Leerlauf		
Param_TestProgrChann87		
5		
Relative load value		
49.664062 %		
Current system status		
SYC_DRIVE		
Param_TestProgrExeConState02UBYTE		
4		
Virtual_SigXSet_TiOff_tiStrtEnd_Off		
48 s		
Engine torque		
118.2 Nm		
<b>DTC memory entry</b>		
Number:	P030200: Cyl.2 Misfire Detected	
Error type 2:	passive/sporadic	
Symptom:	10592	
Status:	00100000	
<b>Standard ambient conditions:</b>		
Date:	11/16/18	
Time:	12:12:21 PM	
Mileage (DTC):	96	
Priority:	2	
Frequency counter:	1	
Elimination counter / driving cycle:	255	
<b>Expanded ambient conditions:</b>		
Engine speed	619.5	1/min
Normed load value	21.960785	%
Vehicle speed	0	km/h
Coolant temperature	77	°C
Intake air temperature	34	°C
Ambient air pressure	1010	mbar
Voltage terminal 30	14.22	V
Dynamic environmental data		

Figure 1. Example of applicable DTC.



# Technical Service Bulletin

---

## Technical Background

Software calibration causing misfire under certain running conditions using winter blend fuel (higher vapor pressure).

## Production Solution

Improved software in development.

## Service

1. If customer's vehicle condition matches the conditions listed in this PSS TSB clear DTC's and test drive vehicle. If there are no faults returned after the test drive, explain to the customer that a solution is forthcoming and currently scheduled for the late 3rd quarter of 2019. No repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*), or through the Technical Assistance Page in Elsa.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2054113) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.