

Technical Service Bulletin

PSS 01 Q8 3.0TFSI Bank 2 engine misfires

01 19 09 2054182/1 March 5, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8	2019	All	3.0TFSI

Condition

This PSS only applies if all of the following conditions are met, see Figure 1 for an example:

- MIL on, MIL flashing, or misfires reported by customer.
- Misfire DTCs are stored for more than one cylinder on Bank 2.
- DTC ambient conditions show misfires occurring at or near same time stamp.
- DTC ambient conditions show misfires occur while engine operating condition is "Leerlauf" (idle in German).
- DTC ambient conditions show misfires occur when vehicle is at or near 0 km/h speed.
- Vehicle is NOT currently misfiring when examined in workshop.

If all of the above criteria are not met, this PSS does not apply and vehicle should be diagnosed using the normal GFF process.

© 2019 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

DTC memory entry		
Number:	P030500: Cyl.5 Misfl	e
Error have 0:	Detected	
Error type 2:	passive/sporadic	
Symptom: Status:	10595 01100000	
	01100000	
Standard ambient conditions: Date:	12/2/18	
Time:	2:42:42 PM	
Mileage (DTC):	1771	
Priority:	2	
Frequency counter:	2	
Elimination counter / driving	Size	
cycle:	255	
Expanded ambient conditions:		
Engine speed	626.5	1/min
Normed load value	7.8431373	%
Vehicle speed	0	km/h
Coolant temperature	101	*C
Intake air temperature	23	*C
Amblent air pressure	970	mbar
Voltage terminal 30	13.1	V
	20 96 27 10 7A 03 11 BD 1	DE 77
Dynamic environmental data	3E FC 05 12 16 03 1F 15 1B 60 00 02 10 10 01 6A	14 04
Unlearning counter according	39	
OBD	35	
Engine status	COENG_RUNNING	
Param_TestProgrCoEngStCOMPUVERBUE		
Engine oil temperature	97.16	•C
Engine operating condition	Leerlauf	
Param_TestProgrChann87	5	
Relative load value	18.726562	%
Current system status	SYC_DRIVE	
Param_TestProgrExeConState02UBYTE	4	122
Virtual_SigXSet_TiOff_tiStrtEnd_Off	2	S
Engine torque	36.2	Nm
DTC memory entry		
Number:	P030600: Cyl.6 Misfli	e .
Freehow Dr	Detected	
Error type 2:	passive/sporadic	
Symptom: Status:	10596	
	01100000	
Standard ambient conditions:	12/2/18	
Date: Time:	2:42:42 PM	
	1771	
Mileage (DTC): Priority:	2	
Frequency counter:	2	
Elimination counter / driving	State .	
cycle:	255	
Expanded amblent conditions:		
Engine speed	626.5	1/min
and the second s	7.8431373	96
Normed load value		
Normed load value Vehicle speed		km/h
Normed load value Vehicle speed Coolant temperature	0	km/h

Figure 1. Example of applicable DTC.

Technical Background

Software calibration causing misfire under certain running conditions using winter blend fuel (higher vapor pressure).

^{© 2019} Audi of America, Inc.

C 2019 Audit of Arhiterica, inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Production Solution

Improved software in development.

Service

- 1. If customer's vehicle condition matches the conditions listed in this PSS TSB clear DTC's and test drive vehicle. If no faults return after the test drive, explain to the customer that a solution is forthcoming and currently scheduled for the late 3rd quarter of 2019. No repairs are necessary at this point.
- 2. Do not replace any components for this condition since this will not resolve the customer's concern.
- 3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance Page in Elsa.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2054182) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2019 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.