



Technical Service Bulletin

91 Laser for Audi Cruise Assist is restricted, DTC C12EBF3 stored in distance control module

91 19 48 2054301/1 March 15, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, and Q8	2019	All	With Audi Cruise Assist

Condition

Customer states:

- The driver assistance systems stopped working. A message for sensor blindness is displayed in the instrument cluster.

Workshop findings:

The following DTC may be stored in the control module for distance control, J428 (address word 0013):

- DTC C12EBF3** (laser for distance control, range recognition restricted) with symptom code 2406.

Technical Background

The laser for distance control sensor cannot penetrate a third party “Car-Bra” (Figure 1) or a protective workshop cover (Figure 2 and 3). This causes the system to indicate “blindness”.



Note:

A vinyl wrap if covering sensors could have an effect on the system.



Figure 1. “Car-Bra”.



Technical Service Bulletin



Figure 2. Protective workshop cover.



Figure 3. Protective workshop cover.

Production Solution

Not applicable.

Service

Check if the DTC time stamp coincides with the vehicle wearing a third party “Car-Bra” or having a protective cover on.

In these cases, clear the DTC.

If it is caused by a “Car-Bra”, instruct the customer that using it can cause the driver assistance systems to become inoperable.

We suggest only to use Audi Genuine Accessories as they have been tested to work in conjunction with all the vehicle’s features.



Technical Service Bulletin

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2054301) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.