

Service Bulletin

Bulletin No.: 18-NA-378

Date: February, 2019

TECHNICAL

Subject: Surge, Chuggle, Fishbite, Shudder Feel During Driving Maneuvers

Drand	Model:	Model Year:		VIN:		Engine	Transmission:
Brand:	woder.	from	to	from	to	Engine:	Transmission.
Cadillac	XT4	2019	2019			2.0L (LSY)	9T50 Automatic (M3H)

Involved Region or Country	North America, Middle East, Israel		
Condition	Some customers may comment on one or more of the following conditions: • Surge • Chuggle • Fishbite • Shudder		
Cause	This condition may be caused by fluid contamination from the stack plate heat exchanger.		
Correction	 Perform a transmission fluid level and condition check. Refer to <i>Transmission Fluid Level and Condition Check</i> in SI. ⇒ If the transmission fluid is found to be milky/cloudy or appears to be contaminated with engine coolant, do the following steps: Replace the transmission. Refer to <i>Transmission Replacement</i> in SI. Replace the transmission fluid cooling exchanger. Refer to <i>Automatic Transmission Fluid Cooling Exchanger Replacement</i> in SI. ⇒ If the transmission fluid is Not showing signs of engine coolant contamination, but has the conditions listed above, do the following steps: Replace the torque converter. Refer to <i>Torque Converter Replacement</i> in SI. Replace the transmission fluid cooling exchanger. Refer to <i>Automatic Transmission Fluid Cooling Exchanger Replacement</i> in SI. Drain the transmission and run on the hoist while manually shifting through all gear ranges for approximately 5-10 minutes. Drain the transmission fluid again and refill the transmission. Important: It may be necessary to drive a minimum of 200 mi (321 km) if slight shudder remains after the repair. Refer to <i>Transmission Fluid Level</i> a minimum of 200 mi (321 km) if slight shudder remains after the repair.		

Parts Information

Note: Only select the parts that coincide with the repair performed.

Causal Part	Description	Part Number	Qty
Х	EXCHANGER, A/TRNS FLUID CLG	24290617	1
N/A	CONVERTER, TORQ (FWD)	24291764	1

Causal Part	Description	Part Number	Qty
N/A	CONVERTER, TORQ (AWD)	24291760	1
N/A	RING, FRT WHL DRV INTER SHF RET	90121202	2
N/A	WASHER, FRT WHL DRV SHF	11611965	2

Causal Part	Description	Part Number	Qty
N/A	NUT, FRT WHL DRV SHF (M27 X 2 X 6H)	11612295	2
N/A	SEAL, TRANS FLUID CLR PIPE (SLIMLINE WASHER 3/8")	25874797	2
N/A	BOLT, TRANS RR MT BRKT	11611642	2
N/A	BOLT, HFH, M10X1.5X75 (TRANS FRT MT)	11588747	2
N/A	BOLT, HFH, M10X1.5X55, 25.7 THD, 22.3 OD, 10.9 STL, GMW3359 (TRANS FRT MT)	11588743	2
N/A	SEAL, PROP SHF TO DIFF CARR INTERFACE	23321677	1
N/A	RETAINER, PROP SHF TO DIFF CARR INTERFACE	23432713	1
N/A	SEAL, PWR TRFER U PROP SHF	23206807	1
N/A	RETAINER, PWR TRFER U PROP SHF	23206808	1
N/A	GASKET, EXH SYS INTER	22816982	1

Causal Part	Description	Part Number	Qty
N/A	TRANSAXLE, AUTO		1
N/A	FLUID, A/TRANS (DEXRON VI) (1QT/0.946 LITRES)	Refer to EPC	Refer to EPC

Warranty Information

Note: Only select the Labor Operation that coincides with the repair performed.

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8464670	Transmission Replacement	Use Published Labor Operation Time
8480808*	Automatic Transmission Fluid Pan Drain and Fill	0.4 hr
Add	Automatic Transmission Fluid Cooling Exchanger and Torque Converter Replacement for FWD	12.8 hrs
Add	Automatic Transmission Fluid Cooling Exchanger and Torque Converter Replacement for AWD	15.8 hrs
*This is a unique Labor Operation for Bulletin use only.		

Version	3
Modified	Released December 17, 2018
	January 22, 2019 – Added the AWD Torque Converter part number to the Parts Information section.
	February 04, 2019 – Added Warranty Information.