

### **Technical Information**

Service

177/18 ENU 5717

# Symptom in Vehicle Interior - Closing Aid for Front Doors Does Not Work at Cold Temperatures (I-no. GZ2): Fitting additional foam part (SY 177/18)

Model Line: Panamera (971)

Model Year: As of 2017 up to 2018

Equipment: Closing aid for doors (I-no. GZ2)

Subject: Front door lock

Symptom: The closing aid for the front doors may not work at negative outside temperatures.

Cause: • Moisture can seep into the lock mechanism and freeze at negative outside temperatures.

If the lock mechanism is "frozen solid", this malfunction can occur.

Remedial Action:

In the event of a customer complaint as described under **Procedure**, fit an additional foam part. The foam part protects the lock mechanism from water and ice.



#### Information

The following points must be observed in relation to the part numbers listed below and the relevant vehicle (depending on equipment):

- Particular/modified components, whose part numbers are listed accordingly, are required for the remedial action.
- Part number indexes will increase over time. Before performing repairs, cross reference with PET (Porsche Spare Parts Catalog), for newer parts (higher index).
- PET must be checked to determine if additional components are needed.

Parts Info: 971.837.735  $\Rightarrow$  Foam part (left)

**971.837.736**  $\Rightarrow$  Foam part (right)


#### Work Procedure: 1 **Preliminary work:**

- 1.1 Remove front door panel on the affected door, see *⇒ Workshop Manual '705919 Removing and installing front door panel'*.
- 1.2 Remove front window guide, see *⇒ Workshop Manual '644519 Removing and installing front window guide'*.
- 1.3 Move the window to its very top position.


Service 5717 ENU 177/18

## **Technical Information**


- 1.4 Remove trim holder  $(\Rightarrow Trim holder 1 -)$ .
  - 1.4.1 Pull holder in ⇒ Trim holder -direction of arrow- so that the clips (⇒ Trim holder -2-) loosen. At the same time, try to lift the holder away from the door lock slightly.
  - 1.4.2 Loosen clip (*⇒ Trim holder* -3-) and remove holder.




- 2.1 Pull film off adhesive strips on the foam part.
- 2.2 Secure the foam part on the door lock as shown.



Trim holder





Foam part

#### 3 Subsequent work:

- 3.1 Install front window guide, see *⇒ Workshop Manual '644519 Removing and installing front window guide'*.
- 3.2 Install front door panel on the affected door, see ⇒ Workshop Manual '705919 Removing and installing front door panel'.

Technical Information		Service		
rechilicarinionnation	1	177/18 ENU	5717	C

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
57174902	Reworking right door lock	
57174901	Reworking left door lock	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	57170	Door lock
Damage type (SA4)	1622	does not close

References: ⇒ Workshop Manual '644519 Removing and installing front window guide'

⇒ Workshop Manual '705919 Removing and installing front door panel'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.