



Technical Service Bulletin

91 SOS Warning displayed in instrument cluster, DTC B18BE13 or B18BD13 stored in the telematics control module

91 19 41 2054038/1 February 28, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7	2019	000001 - 068911	With ConBox

Condition

Customer states:

- A SOS Malfunction indication is shown in the instrument cluster.

Workshop findings:

The following DTC may be stored in telematics control module, J949 (address word 0075):

- **DTC B18BE13** (Mobile communications antenna 2 for emergency call module/open circuit).
- **DTC B18BD13** (Mobile communications antenna 1 for emergency call module/open circuit).

Technical Background

The 4 pole connector pins might have been widened during the assembly process.



Technical Service Bulletin



Figure 1. Telematics Control Module (J949) Connector.

Production Solution

Optimized assembly process.

Service

1. Remove the original 4 pole connector including its pins and remove a section of the vehicle's coaxial wiring for the applicable antenna circuit.

Measure the length of coaxial wiring to be removed based off the adapter antenna cable you are using. This will ensure that the removed section is the same length as the adapter antenna cable (000 098 714).

2. Replace the original 4 pole connector and cable with the new connector harness and pins.
3. Before plugging the new 4 pole connector in, make sure that the telematics control module, J949 (address word 0075) is mounted properly in its bracket.



Note:

Do not tilt the control module while plugging in the 4 pole connector. Tilting the control module while plugging the connector might damage the new pins.



Technical Service Bulletin

4. Clear the DTCs via ODIS.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9128		
Damage Code:	0023		
Labor Operations:	2 Antenna cable repair	9128 4151	See SRT
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	0150 0000	Time stated on diagnostic protocol (Max 20 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2054038/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts and Screws as needed per the Repair Manual	See ETKA/ELSA
VAS6720	Antenna (Aerial) Cable Repair Set	01
4N0035576F	4 pole connector housing for antenna bush plug	01
000098714	Adapter cable	01



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2054038) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.