

SERVICE BULLETIN

Classification: EC19-016 Reference:

ITB19-007

COPYRIGHT© NISSAN NORTH AMERICA, INC. Date:

March 5, 2019

# INFINITI; P0171 AND P0174 SERVICE INFORMATION

 APPLIED VEHICLES:
 2017-2019 Q50 (V37)
 2017-2019 QX60 (L50)

 2017-2019 Q60 (V37)
 2017-2019 QX80 (Z62)

#### SERVICE INFORMATION


Diagnosis for DTCs P0171 (FUEL SYS LEAN B1) and P0174 (FUEL SYS LEAN B2) have been revised for the **APPLIED VEHICLES** listed above. When performing diagnosis for either of these DTCs, start by using the **SERVICE PROCEDURE** section of this bulletin.

**NOTE:** The related Electronic Service Manuals (ESM) will be revised in the future to include these diagnostic steps.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

### SERVICE PROCEDURE

### **FLOW CHART**



## **DTC Confirmation**

### Preconditioning

If DTC Confirmation has been previously conducted, always perform the following before conducting the next test:

- 1. Turn the ignition switch OFF and wait at least 10 seconds.
- 2. Turn the ignition switch ON.
- 3. Turn the ignition switch OFF and wait at least 10 seconds.

### **Testing Condition**

Confirm battery voltage is 11 volts or more at idle before performing **DTC Confirmation**.

### Perform DTC Confirmation

- 4. Clear the mixture ratio self-learning value:
  - a. Connect the CONSULT PC and plus VI to the vehicle.
  - b. Open CONSULT-III plus (C-III plus).
  - c. Start the engine and warm it up to normal operating temperature.
  - d. Go to WORK SUPPORT, and then select SELF-LEARNING CONT.
  - e. Clear mixture ratio self-learning value by selecting CLEAR.
- 5. Turn the ignition switch OFF and wait at least 10 seconds.
- 6. Turn the ignition switch ON.
- 7. Turn the ignition switch OFF and wait at least 10 seconds.
- 8. Start the engine and keep the engine speed between 3,500 and 4,000 RPM for one (1) minute under no load.
- 9. Let the engine idle for 1 minute.
- 10. Keep the engine speed between 2,500 and 3,000 RPM for 20 minutes.
- 11. Check for 1st trip DTC:
  - If DTC P2096, P2097, P2098, or P2099 is stored, replace the corresponding A/F sensor.
  - If no DTCs are stored, continue with the diagnosis in the ESM for P0171 / P0174 <u>excluding A/F</u> <u>sensor</u>.

#### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 5, 2019	ITB19-007	Original bulletin published