



Technical Service Bulletin

01 MIL on, DTC P050700 stored in the ECM

01 19 07 2054025/1 February 26, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7	2019	All	3.0TFSI

Condition

Customer states:

- Engine idle speed abnormally high.
- MIL on.

Workshop findings:

The following DTC is stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P050700** (Idle RPM higher than expected).

Technical Background

ECM/TCM idle torque strategy can cause the rpm to increase under certain driving conditions.

Production Solution

Not applicable.

Service

1. Please perform a throttle body adaption manually through Guided Functions in the 01 Module (ECM).
2. Once successfully adapted, perform test drive to verify idle operation and reoccurrence of any fault codes.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• 1E1 up to 8 Years/80,000 Miles.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 40 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2054025/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2047707) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.