

Technical Service Bulletin

91 MIB2: Lower MMI (HVAC) screen image is distorted or flickering

91 19 39 2053875/1 February 15, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, and Q8	2019	All	With MIB2+

Condition

Customer states:

- The lower MMI / HVAC display is flickering (Figure 1).
- The lower MMI / HVAC display shows streaking colored horizontal lines.

Please review the video example below:

https://audi-

external.kzoplatform.com:443/#/player/medium/1346512489193412091?auto play=on (Figure 1).



Figure 1. QR code for supporting video.

Workshop findings:

In some cases, the following DTC is stored in the Main Unit (address word 005F):

• DTC U10E300 (Multimedia display unit 2 No communication).

Technical Background

A hardware problem in the upper MMI screen causes the image data transferred to the lower screen to be corrupted.

Production Solution

Vehicles built after 12/04/2018 have been screened for this issue.



Technical Service Bulletin

Service

Replace the top display and operating unit in the instrument panel according to the instructions in Elsa.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles.				
	If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	ervice Number: 9193				
Damage Code:	0010				
Labor Operations:	Display and operating unit remove + reinstall	9193 1950	See SRT		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 20 TU)		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
Claim Comment:	nt: As per TSB #2053875/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins listed in this TSB, this includes superseding part numbers!

Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Top display and operating unit	01



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2053875) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.