Reference	SSM74309
Models	E-PACE / X540
	F-PACE / X761
	XE / X760
	XF / X260
Title	AJ20-D4 Engine, MIL Illuminated, P242B-64 logged in PCM
Category	Electrical
Last modified	04-Mar-2019 00:00:00
Symptom	206000 Warning Indicators
Attachments	EGT Location 1.JPG (EGT Location 1.JPG)
	EGT Paint ID 2.jpg (EGT Paint ID 2.jpg)

Content <u>Issue:</u>

Malfunction Indicator Lamp (MIL) illuminated.

DTC P242B-64 logged in Powertrain Control Module (PCM).

Issue applies to AJ20-D4 engine only.

Cause:

The PCM has detected sensor signal plausibility failures because one or more of the Exhaust Temperature Sensors (ETS) installed on the Diesel Particulate Filter (DPF) are loose or dislodged. See list below.

- 1: Temperature sensor pre catalyst Green lead GX73-12B591-AB
- 2: Temperature sensor post catalyst Blue lead HK83-12B591-DA
- **3: Temperature sensor post DPF Orange lead** HK83-12B591-EA (*NAS and EU6D markets only*) See "*SSM Support image 1*" attached to SSM to verify the location of the sensors 1, 2 and 3.

Action:

Check the ETS on the DPF.

- 1. Check if one or more of the sensors are out of location or loose. Note the lead colour (green, blue or orange).
- 2. Take a picture of the issue.
- 3. Visually inspect the sensors and wiring for damage. Replace them if required.
- 4. Verify the sensors have a paint mark across the sensor nut and the DPF boss. If not, make a note on the report. See "SSM Support image 2" attached to SSM.
- 5. Refit the sensors and torque to 35 Nm using a crows foot or slotted socket.
- 6. Clear DTCs and turn the ignition off.
- 7. Wait for 60 seconds.

- 8. Turn the ignition back on and read DTCs.
 - If DTC does not reappear the issue is fixed.
 - If DTC P242B-64 is logged in the PCM, replace the sensors that have been found loose or out of location and repeat actions 6-8.
- 9. Raise EPQR detailing SSM number and attaching the pictures taken.