

# Front Brake Squeal/Squeak (17-in. Rotor 2WD F Sport)

**Service Category** Brake

**Section** Brake (front)

**Market** USA

Lexus Supports  
ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2016 - 2017	IS200T	VDS(s): BA1D2
2018	IS300	VDS(s): BA1D2, C81D2
2014 - 2018	IS350	VDS(s): BE1D2, BZ1D2

## Introduction

Some 2014 – 2018 model year IS350, 2016 – 2017 model year IS200t, and 2018 model year 2WD F Sport vehicles with 17-in. rotors may exhibit a squeal/squeak noise from the front brake pads. This condition may be present at city, highway, and/or parking lot speeds. For customers who find this characteristic objectionable, an updated front brake pad kit and shim kit are available.

## Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
473011	R & R Front Disc, Disc Pads, and Shim Kit (One Side)	0.5	04465-30500	36	99
Combo A	Opposite Side	0.2			

### APPLICABLE WARRANTY

- This repair is covered under the Lexus Basic Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

## Front Brake Squeal/Squeak (17-in. Rotor 2WD F Sport)

### Parts Information

PART NUMBER		PART NAME	QTY
PREVIOUS	NEW		
04465-30500	04465-30510	Pad Kit, Disc Brake, Front	1
04945-30350	04945-30360	Shim Kit, Anti Squeal, Front	1
43512-22260	43512-30350	Disc, Front RH	1
43516-22010	43516-30040	Disc, Front LH	1

### Repair Procedure

1. Confirm the condition exists.
  - A. Is a squeal/squeak noise present from the front brake pads at city, highway, and/or parking lot speeds?
    - **YES** — Continue to substep B.
    - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
  - B. Is the vehicle a 2WD F Sport model with 17-in. rotors?
    - **YES** — Continue to substep C.
    - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
  - C. Are the brake pads BELOW the minimum specification of 1 mm?
    - **YES** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
    - **NO** — Continue to step 2.

## Front Brake Squeal/Squeak (17-in. Rotor 2WD F Sport)

---

### Repair Procedure (continued)

2. Replace the front brake pad kit, shim kit, and disc.

A. Remove the front brake pad kits.

Refer to TIS, applicable model and model year Repair Manual:

- 2014 – 2018 IS350:  
*Brake – Brake (front)* – [“Brake \(Front\): Front Brake\(for 2GR-FSE, 8AR-FTS\): Removal”](#)
- 2016 – 2017 IS200t:  
*Brake – Brake (front)* – [“Brake \(Front\): Front Brake\(for 2GR-FSE, 8AR-FTS, 2GR-FKS\): Removal”](#)
- 2018 IS350:  
*Brake – Brake (front)* – [“Brake \(Front\): Front Brake\(for 2GR-FSE, 8AR-FTS, 2GR-FKS\): Removal”](#)

B. Install the NEW front brake pad kit, shim kit, and disc and reinstall the front brake components.

Refer to TIS, applicable model and model year Repair Manual:

- 2014 – 2018 IS350:  
*Brake – Brake (front)* – [“Brake \(Front\): Front Brake\(for 2GR-FSE, 8AR-FTS\): Installation”](#)
- 2016 – 2017 IS200t:  
*Brake – Brake (front)* – [“Brake \(Front\): Front Brake\(for 2GR-FSE, 8AR-FTS, 2GR-FKS\): Installation”](#)
- 2018 IS350:  
*Brake – Brake (front)* – [“Brake \(Front\): Front Brake\(for 2GR-FSE, 8AR-FTS, 2GR-FKS\): Installation”](#)

3. Confirm the squeal/squeak noise is no longer present.