

<b>Reference</b>	SSM73872
<b>Models</b>	Discovery / L462 Discovery Sport / L550 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494 Range Rover Velar / L560
<b>Title</b>	Emergency call button does not illuminate when carrying out PDI activation
<b>Category</b>	Electrical
<b>Last modified</b>	05-Mar-2019 00:00:00
<b>Symptom</b>	207000 Entertainment Systems
<b>Content</b>	<p><b>Issue:</b> When carrying out the Pre Delivery Inspection routine using Pathfinder the e-call button may not illuminate and/ or 'SOS is not available' displayed on the instrument Cluster' due to activation failure.</p> <p><b>Cause:</b> An error with the in-market database may prevent the Telematics Control Unit (TCU) changing the operational mode to 'Activated' from 'Pre-activated'.</p> <p><b>Action:</b> If the TCU activation fails during the PDI, please carry out the following steps:</p> <ol style="list-style-type: none"><li>1. Ensure the engine is running</li><li>2. Run the Telematics server check</li><li>3. Continue the PDI process using Pathfinder.</li><li>4. After successful activation, turn off the ignition</li></ol> <p><b>Note:</b> If the vehicle does not successfully activate TCU Connected Car services after carrying out the above steps, please raise a Technical Assistance including the following details:</p> <ol style="list-style-type: none"><li>1. Session files.</li><li>2. Confirmation of process followed and the SSM number above.</li><li>3. Date/ time of all manual activation attempts.</li><li>4. Vehicle VIN.</li><li>5. TCU serial number and photograph of the TCU label.</li></ol> <p>VIN range as follows:</p> <p>L538: 18 MY - SALVA2BN0JH303573 onwards L538c: 18 MY - SALVA5AN5JH299779 onwards L550: 18 MY - SALCA2BN9JH751611 onwards L494: 18 MY - SALWR2RE1JA181320 onwards L462: 18 MY - SALRA2BK9JA047488 onwards L405: 18 MY - SALGS2RE5JA380217 onwards L560: 18MY - SALYA2BK3JA700125 onwards</p>

