



LTB01290NAS1

TECHNICAL BULLETIN

20 MAR 2019

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

413-01

SUBJECT/CONCERN:

Incorrect French Language Translation For 'Deactivated Park Brake' Message

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2018 Onwards	684395 Onwards	Halewood
Range Rover Evoque (LV)	2018-2019	226559-354461	Halewood

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

On vehicles with a partial Thin Film Transistor (TFT) Instrument Cluster (IC) only, the French language translation of the 'Deactivated Park Brake' message may be incorrect.

CAUSE:

This may be caused by the incorrect translation message in the translation file.

ACTION:

Should a customer express this concern, follow the procedure(s) below.

PARTS:

No Parts Required

TOOLS:



E192494

Jaguar Land
Rover-approved
battery power
supply



E208514

Jaguar Land
Rover-approved
diagnostic
equipment with
latest
PATHFINDER
software

WARRANTY:

 **NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.
- The JLR claims submission system requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Instrument Cluster (IC) - Update ECU	86.95.61	1.0	04	LR115495

 **NOTE:**

Normal Warranty procedures apply.

DIAGNOSTIC PROCEDURE: **CAUTIONS:**

- A Jaguar Land Rover-approved battery power supply must be connected to the vehicle startup battery.
- All ignition ON/OFF requests **MUST** be performed; failure to do these steps may cause damage to vehicle control modules.

 **NOTE:**

Use the Jaguar Land Rover claims submission system for Field Service Action program eligibility requiring an Instrument Panel Cluster Control Module [IPC] software update. If eligible, perform and claim the update as per that program using the latest PATHFINDER software.

1 Connect the Jaguar Land Rover-approved battery power supply to the vehicle startup battery.

2  **NOTE:**

The Jaguar Land Rover-approved diagnostic equipment must be loaded with PATHFINDER version 224 (or later).

Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.

3

 **NOTE:**

The Jaguar Land Rover-approved diagnostic equipment will read the correct Vehicle Identification Number (VIN) for the current vehicle and automatically take the vehicle out of Transit mode (if required).

Follow all on-screen instructions.

4

Select **ECU Diagnostics**.

5

Select **Instrument Panel Cluster Control Module [IPC]**.

6

Select **Update ECU**.

1 Follow the on-screen instructions until the application finishes successfully.

7

Exit the current session.

1 If required, reset the vehicle to **Transit mode**.

2 Select the **Exit** icon.

8

Disconnect the diagnostic equipment and battery power supply from the vehicle.