

| GROUP | MODEL | | |
|--------|--------------------------|--|--|
| ENG | See Model List on Page 1 | | |
| NUMBER | DATE | | |
| 205 | April 2019 | | |

TECHNICAL SERVICE BULLETIN

SUBJECT:

SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (\$A379)

This bulletin provides information related to an expanded diagnostic test that is now required on a number of vehicles previously diagnosed with Diagnostic Trouble Code ("DTC") P1326. Using the procedures published in TSB PI1802W/X and PI1803W/X, the subject vehicles were diagnosed and determined to require an engine replacement and are currently being held at dealers pending repair.

As a result of additional field data collection and analysis, the initial diagnosis method has been updated to improve test result accuracy. Prior to performing an engine replacement on any of the VINs affected by this Service Action, the engine condition needs to be re-assessed utilizing an updated/expanded diagnostic process. Follow the procedure outlined in this bulletin to determine the engine's condition and then complete the repair by reverting back to TSB PI1802W/X and PI1803W/X (depending on model/model year) for instructions to either install the wiring harness or to replace the engine.

Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.

| Campaign Year | | Model | Engine | Production Date | |
|---------------|-----------|-----------------------|-------------------|--------------------|--|
| | 2014 | Optima (TF) | 2.4L GDI | 8/29/13 - 4/25/14 | |
| PI1802W/X | 2015-2018 | Optima (TF/QF/JF/JFa) | 2.4L & 2.0L T-GDI | 4/16/14 - 7/11/18 | |
| PITOUZVV/A | 2014-2018 | Sportage (SL/QL) | 2.4L & 2.0L T-GDI | 9/30/13 - 4/5/18 | |
| | 2015-2018 | Sorento (XMa/UMa) | 2.4L & 2.0L T-GDI | 1/3/14 - 3/7/18 | |
| | 2011-2013 | Optima (QF/TF) | 2.4L & 2.0L T-GDI | 8/12/10 – 9/27/13 | |
| PI1803W/X | 2014 | Optima (QF) | 2.4L & 2.0L T-GDI | 8/28/13 - 5/15/14 | |
| FIIOUSVV/A | 2011-2013 | Sportage (SL) | 2.0L T-GDI | 12/30/10 - 8/30/13 | |
| | 2012-2014 | Sorento (XMa) | 2.4L GDI | 4/19/11 – 2/10/14 | |

* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service \rightarrow Warranty Coverage \rightarrow Warranty Coverage Inquiry \rightarrow Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs \rightarrow Not Completed Recall \rightarrow Recall VIN \rightarrow Select Report), which includes a list of affected vehicles.

This issue number is SA379.

File Under: <Engine>


☑ Service Advisors ☑ Technicians ☑ Body Shop Manager ☑ Fleet Repair

SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (\$A379)

* IMPORTANT

All parts orders will be validated by the KDS test results (Wiring Signal Interference Test AND Engine Noise Test) per this bulletin. Only parts orders with valid test results or Techline approval will be allocated. If test results are not confirmed via KDS within fourteen (14) business days of the launch of this bulletin or the Parts order (whichever is later), the parts order may be deleted.

Flow Chart:



Note: If any concerns arise after completing the flow chart, open a Techline case online.

PI1802W/X: Wiring Harness Install – page 12; Engine Replacement – page 17 PI1803W/X: Wiring Harness Install – page 12; Engine Replacement – page 16

MORE >

ECU Upgrade

Actuation

Techline Feedback


SUBJECT:

SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (\$A379)

KD5

Wiring Signal Interference Check Procedure:

- Using the KDS (connected to the internet), perform a Fault Code Search and confirm DTC P1326 is present.
 - If P1326 is or was present, proceed to the next step to perform the wiring signal interference check.
 - If the engine is seized or severely knocking, proceed to the engine replacement procedure in PI1802W/X (page 17) or PI803W/X (page 16) (with Techline authorization per Flow Chart).
- Start/warm up the engine and ensure <u>ENGINE OIL</u> is at operating temperature (176°F).



Fault Code Searching

From the KDS Home Screen, select S/W Management.




4. Select Engine Control → Wiring Signal Interference Check.



TSB: SA379 Multiple Models April 2019


SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (SA379)

 Ensure the engine is on and at idle and <u>ENGINE OIL</u> temperature is at 176°F degrees or higher. Select OK to proceed.



5b. Select OK to proceed.


NOTE: This test should only be performed if Knock Sensor Detection System - ECU Logic Improvement (PI1803) has previously been completed.



5c. If the conditions are not met, a pop-up as shown will be displayed.




6. Enter vehicle mileage and RO number (VIN is automatically populated).




SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (SA379)


 Wiring Signal Interference Check test will begin and take about three (3) minutes to complete. NOTE: <u>Do not</u> push on the accelerator pedal.



 If the result is "OK", turn the engine off and proceed to the Engine Noise Inspection procedure below.




 If the result is "NOT OK", turn the engine off and proceed to <u>step 2</u> of the Knock Sensor (KS) Extension Harness Installation procedure on PI1802W/X (page 12) or PI803W/X (page 12).



Engine Noise Inspection Procedure:

- Prior to inspection, ensure the KDS is fully charged and is connected to the internet <u>every day</u> to ensure the latest update is received and installed.
 - Engine oil level should be at the "FULL" mark. Top off with 5W-30 if required.
 - Test requires the engine to be in satisfactory running condition and able to idle normally.
 - Engine coolant temperature should be above minimum test temperature: 185°F (85°C).




If the engine's running condition is poor due to issues unrelated to a connecting rod knocking noise (faulty sensors, intake/exhaust manifold leak, catalytic converter, etc.), diagnose and repair prior to performing this inspection procedure. If the engine cannot be tested or has other major concerns, see Warranty Claim Authorization information on PI1802W/X (page 40) or PI1803W/X (page 30).

SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (\$A379)

2. With the engine off, remove the dipstick (A).

* NOTICE

Engine cover removed in images for demonstration-only purposes.




Insert the engine noise tester SST adapter (B) into the dipstick tube then start and idle the engine.

* NOTICE


To avoid false readings, ensure the adapter (B) is properly inserted into the dipstick tube and that the tube is not in contact with the intake manifold.


If the dipstick tube is not centered and is close to or touching the manifold, carefully adjust (bend) and center the dipstick tube with a pry bar.




Click here for a video tutorial of the Inspection Procedure.

 Connect the 3.5 mm male end of the engine noise tester SST (C) to the 3.5 mm female end of the extension cable (D).








SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (\$A379)


Attach the SST clip of the extension cable (D) to the hood latch.

* NOTICE

Make sure to route the extension cable away from moving parts (pulleys, fan, and belts and be careful not to get it pinched between door and body or window, etc.).




6. Connect the 3.5 mm male end (E) of the extension cable to the headphone port located at the upper left corner (KDS version 1.0) or at the bottom of the tablet (KDS version 2.0).



 Connect the VCI-II to the OBD-II connector and launch the KDS application from the KDS tablet home page.



8. Confirm communication with VCI (F) and then configure the vehicle (G) using the **AUTO VIN** (H) feature.




TSB: SA379 Multiple Models April 2019

SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (SA379)

9. Swipe up the "More" tab from the lower screen of the KDS and select "Special Inspection".

* NOTICE

If the vehicle model/model year does not qualify for this campaign, a message will pop up; if so, verify that the vehicle is included in the list of affected VINs.




- 10. Complete the vehicle information form on the screen:
 - Mileage
 - RO number
 - Select "Verify" to verify the VIN


Note: VIN must be verified with the "Verify" function in order to proceed to the next step.

Select "Next" to continue.

- 11. Confirm that all of the pre-inspection items listed on the screen are true:
 - Engine Oil Level Normal
 - Coolant Level Normal
 - Engine Cover Installed
 - Driver Window Opened
 - A/C & Blower Motor OFF
 - Audio & All Accessories OFF
 - Engine Warm up (185°F or higher)
 - Insert "A" into dipstick tube
 - Connect "B" part at tablet headphone port

Select "Next" after checking items mentioned above.







SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (SA379)

- 12. The program will automatically check the engine sensors' data. Select the "Next" button if all the conditions are satisfied.
 - Engine Coolant Temperature: 185°F or higher
 - A/C Request to ECU: OFF

Note: If the test item result is "NOT GOOD", correct the condition then select "Refresh Data".



13. Follow the instructions on the screen then select "Next".




14. Prior to the initial measurement, the program will automatically check if the engine noise tester is installed and operating correctly at engine idle and perform an internal diagnosis.

Begin the second part of the engine noise tester check by selecting "Start".



If the measured noise level is too low or abnormally high, an engine noise tester inspection message will pop up. Check and correct as necessary and start again.




SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (SA379)

 With the vehicle in Park (A/T) / Neutral (M/T), increase and maintain the engine speed at 2,000-3,000 RPM for thirty (30) seconds.


> The program will automatically proceed to the next step when the engine noise tester is ready.

* NOTICE

Once the RPM is in the specified range, the time count (green bars) will be initialized.



- 16. With the vehicle in Park (A/T) / Neutral (M/T), begin the "2000rpm Test" by increasing and maintaining engine speed between 1,900-2,100 (2.4L) or 1,900-2,200 (2.0T) RPM until all three (3) measurements are complete.
- When the "2000rpm Test" is complete, release the accelerator pedal so that engine maintains idle state for the "Idle Test".
- 18. The "Idle Test" will automatically begin. Keep the engine at idle and wait until all three (3) measurements are complete.






SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (SA379)


- After the completion of the engine noise inspection, the KDS will automatically generate/display a "PASS" or "NO PASS" result.
 - If the inspection result is "PASS", proceed to the KS Extension Harness Installation procedure in PI1802W/X (page 12) or PI1803 (page 12).
 - If the inspection result is "NO PASS," proceed to the Engine Replacement Procedure in PI1802W/X (page 17) or PI1803W/X (page 16)
 - If the inspection result is "RETEST" with an error code, see Adapter Error Code chart in Appendix 1 on page 13 for corrective action then repeat the inspection procedure starting from step 9.
- 20. Select "Finish" to complete the engine noise inspection. Ensure the KDS is connected to the internet and the "Special Inspection" KDS application is open to automatically submit the results to the Kia Server. To save and/or print the results as PDF, select "Print".

If the KDS is not connected to the internet, up to five (5) results will stay pending in the queue until the KDS is connected to the internet with the "Special Inspection" application open.

Note: The five (5) pending results must be submitted before a sixth (6th) test can be conducted.







21. Disconnect the engine noise tester from the KDS and carefully remove the adapter (B) from the dipstick tube by grasping the engine noise tester adapter. Refer to PI1802W/X or PI1803W/X to continue repair with Engine Replacement or Wiring Harness install.

PI1802W/X: Wiring Harness Install – page 12; Engine Replacement – page 17 PI1803W/X: Wiring Harness Install – page 12; Engine Replacement – page 16

SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (\$A379)

PI1802W/X AFFECTED VEHICLE RANGE:

| Model | Production Date Range | | |
|-------------------------------|--|--|--|
| 14MY Optima (TF) | August 29, 2013 through April 25, 2014 | | |
| 15-18MY Optima (TF/QF/JF/JFa) | April 16, 2014 through July 11, 2018 | | |
| 14-18MY Sportage (SL/QL) | September 30, 2013 through April 5, 2018 | | |
| 15-18MY Sorento (XMa/UMa) | January 3, 2014 through March 7, 2018 | | |

PI1803W/X AFFECTED VEHICLE RANGE:

| Model | Production Date Range | | |
|------------------------|--|--|--|
| 11-13MY Optima (QF/TF) | August 12, 2010 through September 27, 2013 | | |
| 14MY Optima (QF) | August 28, 2013 through May 15, 2014 | | |
| 12-14MY Sorento (XMa) | April 19, 2011 through February 10, 2014 | | |
| 11-13MY Sportage (SL) | December 30, 2010 through August 30, 2013 | | |

REQUIRED TOOL:

| Tool Name | Tool Part No. | Figure | Comments |
|----------------------------|---------------|--------|---|
| Engine Noise Tester SST | GIT1XTDCP005 | 1/4 | Auto-shipped to Dealers in June 2017 for SC147 For replacements, contact Snap-On Business Solutions at (888) 542-1011. |

WARRANTY INFORMATION:

N Code: N99 C Code: C99

| Model | Claim Type | Causal P/N | Qty. | Repair Description | Labor Op Code | Op Time | Replacement P/N | Qty. |
|--|---------------|----------------|------|---|------------------|------------|--------------------|------|
| Opt. (TF, JF), Spo. (SL, QL | V | 23060 2G400 | 0 | (SA379) Wiring Harness & Engine Noise Inspection (KMC VIN) | 190027R0 | 0.5 M/H | N/A | N/A |
| Opt. (QF, JFa), Sor. (XMa, UMa) | V | 23060 2G400 | 0 | (SA379) Wiring Harness & Engine Noise Inspection (KMMG VIN) | 190A10R0 | 0.5 M/H | N/A | N/A |

* NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference <u>SA379</u> when accessing the WebDCS system.

SERVICE ACTION: WIRING SIGNAL INTERFERENCE CHECK & ENGINE NOISE INSPECTION (\$A379)

Appendix 1 (Engine Noise Adapter Threshold)

| Code | Concern | Action | | |
|-----------------|--|---|--|--|
| RETEST Code 001 | Any measured value out of range / below lower limit Contact GIT Ameri | | | |
| RETEST Code 002 | RETEST Code 002 Any measured value out of range / over upper limit | | | |
| RETEST Code 003 | Difference between minimum and maximum of 2000 RPM or Idle RPM measured value out of range | Perform Retest three (3) more times. If Error Code 003 still displays after the third attempt, contact GIT America. | | |
| RETEST Code 004 | Difference between minimum and maximum of 2000 RPM <u>and</u> Idle RPM measured value out of range | Perform Retest three (3) more times. If Error Code 004 still displays after the third attempt, contact GIT America. | | |
| RETEST Code 005 | The adapter/extension cable is unplugged or damaged after test started | Perform Retest three (3) more times. If Error Code 005 still displays after the third attempt, contact GIT America. | | |

GIT America can be contacted at (888) 542-4371.