



TECHNICAL SERVICE BULLETIN

Illuminated MIL With DTC P0128 - Built On Or Before 19-Feb-2019

**19-
2116**
16 April
2019

Model:

Ford 2016-2019 Fiesta

Issue: Some 2016-2019 Fiesta vehicles with a 1.6L twin independent variable cam timing (Ti-VCT) engine built on or before 19-Feb-2019 may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P0128 stored in the powertrain control module (PCM). This may be due to some PCM software parameters related to engine temperature. To resolve the condition, reprogram the PCM.

Action: Follow the Service Procedure steps to correct the condition on vehicles that meet all of the following criteria:

- 2016-2019 Fiesta
- 1.6L Ti-VCT engine
- Built on or before 19-Feb-2019
- The only DTC stored in the PCM is P0128

Warranty Status: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2016-2019 Fiesta 1.6L Ti-VCT: Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Operations)	192116A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	RECALEM
Condition Code:	04

Service Procedure

1. Reprogram the PCM to the latest calibration using the latest software level of the appropriate Ford diagnostic scan tool.

NOTE: ADVISE THE CUSTOMER THAT THIS VEHICLE IS EQUIPPED WITH AN ADAPTIVE TRANSMISSION SHIFT STRATEGY WHICH ALLOWS THE VEHICLE'S COMPUTER TO LEARN THE TRANSMISSION'S UNIQUE PARAMETERS AND IMPROVE SHIFT QUALITY. WHEN THE ADAPTIVE STRATEGY IS RESET, THE COMPUTER WILL BEGIN A RELEARNING PROCESS. THIS RELEARNING PROCESS MAY RESULT IN FIRMER THAN NORMAL UPSHIFTS AND DOWNSHIFTS FOR SEVERAL DAYS.

© 2019 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.