GLOBAL SAFETY FIELD INVESTIGATIONS DCS5004 URGENT - DISTRIBUTE IMMEDIATELY

Date: March 27, 2019

Subject: N182205680-01 - Service Update

Transmission Stacked Plate Heat Exchanger Leak

Revised Parts, Service Procedure and Warranty Information

Models: 2019 Cadillac XT4

Equipped with Automatic Transmission (RPO M3H)

To: All General Motors Dealers

This bulletin has been revised to update the parts information, labor time and service procedure. Please discard all copies of N182205680.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS

Service Update

N182205680 Transmission Stack Plate Heat Exchanger Leak



Release Date: March 2019 Revision: 01

Review Description: This bulletin has been revised to update the parts information, labor time and service

procedure. Please discard all copies of N182205680.

Attention: This service update involves vehicles in dealer inventory only and will expire March 31, 2020.

| | | Model Year | | Model Year | | | |
|----------|-------|------------|------|------------|--------------------------------|--|--|
| Make | Model | From | То | RPO | Description | | |
| Cadillac | XT4 | 2019 | 2019 | МЗН | Transmission-Auto 9 SPD, 9T50, | | |
| | | | | | ETRS GEN 1 | | |

This service update should be performed on vehicles in dealer inventory only. Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

| Condition | Certain 2019 model year Cadillac XT4 vehicles may have been manufactured with a stacked plate heat | | | | |
|------------|--|--|--|--|--|
| | exchanger (SPHE) that has the potential to develop a leak. A leaking SPHE can contaminate the | | | | |
| | automatic transmission fluid with engine coolant, resulting in poor transmission shift quality like shudder, | | | | |
| | hard shifts, vibration, or surging that typically will not provide malfunction indication (no DTCs set). | | | | |
| Correction | Dealers are to replace the stacked plate heat exchanger. | | | | |

Parts

| Quantity | Part Name | Part No. |
|----------|---------------------------------|---|
| 1 | Exchanger-A/Trans Fluid Cooling | 24290617 |
| 2 | Seal-Trans Fluid Cooler Pipe | 25874797 |
| 1 | Dex-Cool (Gallon) | 12346290 (US) 10953464 (Canada) Obtain Local Equivalent-(EXPORT) |
| 1 | ATF Dexron VI | 88865601 (US) 19367328 (Canada) Obtain Local Equivalent-(EXPORT) |

Parts Pre-Ship Information

Important: An initial supply of 24290617 - Exchanger-A/Trans Fluid Cooling required to complete this recall will be preshipped to involved dealers of record. This pre-shipment is scheduled to take place the week of March 8, 2019. Preshipped parts will be charged to dealer's open parts account. **All orders placed prior and during the pre-ship will be cancelled.**

When ordering additional 24290617 order parts on a CSO = Customer Special Order only. DRO's may be cancelled. **All orders will be reviewed prior to being filled.** A quantity limiter may be in effect.

Before ordering the additional parts listed on bulletin, if required, check your dealer inventory as this may be available at your dealership already.

Note: Due to limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.

Attention: This service update involves vehicles in dealer inventory only and will expire March 31, 2020.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information


| Labor | | Labor | Trans. | Net |
|-----------|--|-------|--------|------|
| Operation | Description | Time | Type | Item |
| 9104315 | Automatic Transmission Fluid Cooling Exchanger Replacement | 2.6 | ZFAT | N/A |

Service Update

N182205680 Transmission Stack Plate Heat Exchanger Leak



Service Procedure



TIP: With the battery tray removed, release the charge air cooler inlet air tube fasteners (1,2). Rotate the charge air cooler inlet air tube outward, this will allow access to the lower charge air cooler inlet air tube fastener. Using this tip, it is not necessary to remove the fascia, wheel house liner or structure brace.

Replace the automatic transmission fluid cooling exchanger. Refer to *Automatic Transmission Fluid Cooling Exchanger Replacement* in SI.

Dealer Responsibility

Dealers must take the steps necessary to ensure that the service update correction has been made to all involved vehicles in dealer inventory before selling or dealer-trading the vehicle, but no later than March 31, 2020.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.