

Service

Category Drivetrain

Section Automatic Transmission/Transaxle

Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2018 - 2019	LS500	

REVISION NOTICE

April 8, 2019 Rev1:

- Applicability has been updated to include 2019 model year LS500 vehicles.
- The entire bulletin has been updated.

Any previous printed versions of this bulletin should be discarded.

Introduction

Some 2018 – 2019 model year LS500 vehicles may exhibit one or both of the following transmission-related conditions:

- R to D shift delay when vehicle is cold
- Shift bump when slowing to a stop

The Engine Control Module/ECM (SAE Term: Powertrain Control Module/PCM) logic has been revised to address these conditions. Follow the Repair Procedure in this bulletin to address these conditions.

Rev1

Page 2 of 6



Transmission Drivability Concerns

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EG1818	Reprogram ECM (PCM)	0.4	89661-50S31 89661-50S91 89661-50J61 89661-50V01	99	74

APPLICABLE WARRANTY

- This repair is covered under the Lexus Federal Emission Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	MODEL YEAR	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
LS500	2019 -	2WD	JTHB51FF#K5007988
		4WD	JTHC51FF#K5005999

Parts Information

MODEL YEAR DRIVETRAIN		PART NUMBER		PART NAME	QTY
WIODEL YEAR	DRIVEIRAIN	PREVIOUS	NEW	PARI NAME	QII
2018	2WD	89661-50S31	89661-50S32		
2016	4WD	89661-50S91	89661-50S92	Computer, Engine Control	
2WD		89661-50J60	89661-50J61	(ECM/PCM)	_
2019	4WD	89661-50V00	89661-50V01		
_	_	00451-00001-LBL		Authorized Modifications Labels	1

NOTE

- The ECM (PCM) should NOT be replaced as part of the Repair Procedure.
- Authorized Modifications Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through *Dealer Daily Parts Dealer Support Materials Orders*.

L-SB-0039-18

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*		TS2UNIT	
Techstream Lite	ADE	TSLITEPDLR01	1
Techstream Lite (Green Cable)		TSLP2DLR01	

^{*}Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 14.00.019 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- Use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit <u>techinfo.toyota.com</u> for more information regarding J2534 reprogramming.

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
GR8 Battery Diagnostic Station*	00002-MCGR8	1

^{*}Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.



Calibration Information

MODEL	MODEL YEAR	DRIVETRAIN	ECU TYPE	CALIBRATION ID		
WODEL				PREVIOUS	NEW	
	2018	2WD	Main	8966350K6000 8966350K6100	8966350K6200	
			Sub	896655065000 896655065100	<u>896655065200</u>	
			ECT	8966A5005000 8966A5005100	8966A5005200	
		4WD	Main	8966350L2000 8966350L2100	8966350L2200	
LS500			Sub	896655071000 896655071100	896655071200	
			ECT	8966A5011000 8966A5011100	8966A5011200	
	2019	2WD	Main	896635022000	<u>896635022100</u>	
			Sub	896655082000	<u>896655082100</u>	
			ECT	8966A5016000	8966A5016100	
		4WD Sub ECT	Main	896635064000	<u>896635064100</u>	
			Sub	896655083000	<u>896655083100</u>	
			ECT	8966A5017000	8966A5017100	

Repair Procedure

1. Confirm the condition(s) exists.

Does the vehicle exhibit ANY of the conditions listed in the Introduction?

- YES Continue to step 2.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.




Page 5 of 6

Transmission Drivability Concerns

Repair Procedure (continued)

- 2. Use Techstream to confirm if the ECM (PCM) calibration has been updated and check for the Authorized Modifications Label affixed to the vehicle in the location shown below.
 - Is the calibration ID listed in Techstream and on the label the latest ECM (PCM) calibration?
 - YES This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
 - NO Continue to step 3.

Figure 1. Location of Authorized Modifications Label for 2018 – 2019 LS500



1	Replacement ECM (PCM) Part Number (e.g., 89661-50S32)
2	New Calibration ID(e.g., 8966350K6200)
3	Dealer Code

4	Completed Date
5	This SB Number



Repair Procedure (continued)

Flash reprogram the ECM (PCM).

L-SB-0039-18

NOTE

- The GR8 battery diagnostic station MUST be used in Power Supply Mode to maintain battery voltage at 13.5V while flash reprogramming the vehicle.
- For details on how to use the GR8 battery diagnostic station, refer to the GR8 Instruction Manual located at TIS - Diagnostics - Tools & Equipment - Battery Diagnostics.

Follow the procedures outlined in Service Bulletin T-SB-0134-16, Techstream ECU Flash Reprogramming Procedure, and flash the ECM (PCM) with the NEW calibration file update.

- 4. Prepare and install the Authorized Modifications Label.
 - A. Using a permanent marker, enter the following information on the label:
 - ECM part number [Refer to the Parts Information section for the NEW PART NUMBER
 - Calibration ID(s) [Refer to the **Calibration Information** section for the **NEW CALIBRATION ID**
 - **Dealer Code**
 - Repair Date
 - Change Authority [This bulletin number]
 - B. Install the Authorized Modifications Label on the vehicle at the location shown in Figure 1. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.
- 5. Start the engine and warm it up to normal operating temperature.
- 6. Test-drive the vehicle to confirm proper operation.