GLOBAL SAFETY FIELD INVESTIGATIONS DCS5015 URGENT - DISTRIBUTE IMMEDIATELY

Date: April 15, 2019

Subject: N192219210 - Service Update Transmission Torque Converter

Models: 2019 Chevrolet Sonic

To: All General Motors Dealers

General Motors is releasing Service Update N192219210 today. The total number of U.S. vehicles involved is approximately 27. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated April 15, 2019. A list of involved vehicles is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS

Service Update N192219210 Transmission Torque Converter



Release Date: April 2019

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Sonic	2019	2019		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2019 model year Chevrolet Sonic vehicles may have a torque converter housing hole drilled too deep.
Correction	Dealer to insert an adhesive coated bolt to prevent external leaks.

Parts

Quantity	Part Name	Part No.	
1	Bolt	11588468	


It is estimated that only 27 involved vehicles will require parts replaced. Due to the small number of vehicles anticipated that will need this fix and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9104422	Install Bolt in Transmission	0.3	ZFAT	N/A

Service Procedure



- 1. Lift the vehicle. Refer to Lifting and Jacking the Vehicle in SI.
- 2. Locate the threaded bolt hole in the front of the transmission as shown above.
- 3. Install the provided bolt in the hole and torque to 19Ft-lbs (25N-m).
- 4. Lower the vehicle. Refer to *Lifting and Jacking the Vehicle* in SI.

Service Update N192219210 Transmission Torque Converter



Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



We Support Voluntary Technician Certification