GLOBAL SAFETY FIELD INVESTIGATIONS DCS5016 URGENT - DISTRIBUTE IMMEDIATELY

Date: April 16, 2019

Subject: N192216390 - Service Update

Incorrect Lower Control Arm Installed

Models: 2019 Cadillac CTS

To: All General Motors Dealers

General Motors is releasing Service Update N192216390 today. The total number of U.S. vehicles involved is approximately 4. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated April 16, 2019. A list of involved vehicles is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS

Service Update

N192216390 Incorrect Left Lower Control Arm Installed



Release Date: April 2019 Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year		Model Year			
Make	Model	From	То	RPO	Description		
Cadillac	CTS	2019	2019				

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2019 model year Cadillac CTS vehicles may have an incorrect left front lower control arm.	
Correction Dealers will replace the left front lower control arm.		

Parts

Quantity	Part Name	Part No.	
1	Bolt	11611268	
1	Front Lower Control RR Link, Left	23462014	

It is estimated that only 4 involved vehicles will require parts replaced. Due to the small number of vehicles anticipated that will need this fix and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Туре	Item
9104425	Front Lower Control Rear Link Replacement	0.9	ZFAT	N/A
	Add: Front End Alignment	0.7		

Service Procedure

Replace the Front Lower Control Rear Link. Refer to Front Lower Control Rear Link Replacement in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

