

Service Bulletin

Bulletin No.: 18-NA-301


Date: April, 2019

TECHNICAL

Subject: Service 4WD Lamp Message Displayed - DTC C119B 04, P0700, and/or P2534 Set

Brand: Model:	Modeli	Model Year:		VIN:		Engine:	Transmission:
	woder.	from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2019			L84, L87	
GMC	Sierra 1500 (New Model)					·	

Involved Region or Country	North America, Middle East, South America, North Africa and Thailand (ASEAN).	
Additional Options (RPOs)	F48 , NPO and NQH.	
Condition	Some customers may comment that the Service 4WD light is on. Some technicians may find one or more of the following DTC's set: C119B 04: Front Axle Engagement Feedback Switch Circuit set in the TCM P0700: Transmission Control Module Requested MIL Illumination P2534: Ignition On/Start Switch Circuit Low Voltage set in the ECM	
Cause	This condition may be caused by the front axle actuator pulling over 5 amps, blowing the fuse.	



Correction

4698775

Locate fuse #47 and/or #83 in the Front Compartment Fuse Block. Refer to Document ID: 4694932 in SI.

- Replace fuse #47: Transmission control module ignition with a 10A fuse.
- Replace fuse #83: FTZM with 30A fuse.
- · Install new fuse block cover.
- New cover reflects the changes to the fuses for two circuits.

Parts Information

Causal Part	Description	Part Number	Qty
Х	FUSE, 10 A	19209792	1
Х	FUSE, 30 A	19209796	1
N/A	COVER, ENG WRG HARN J/BLK	84594612	1

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5480658*	Diagnosis Time and Fuse Replacement for Fuse #47 and #83	0.5 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	2
Modified	Released January 17, 2019 Revised April 01, 2019 - Add Unique Labor Op number.