

**Subject: Engineering Information – Left, Right and/or Both Ground Effects Rockers are Loose and/or Pulling Away from Body of Vehicle**

**Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2018	2019				

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPO's)</b>	Equipped with ACCESSORY-GROUND EFFECTS PACKAGE - ALTERNATE DESIGN (RPO 5VM)
<b>Condition</b>	<b>Important:</b> If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI. Some customers may comment on the left, right and/or both ground effects rockers are loose and/or pulling away from the body of the vehicle.
<b>Cause</b>	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

### Correction

If you encounter a vehicle with the above concern, document by taking pictures of the ground effects rockers being loose and/or pulling away from the body of the vehicle, and contact the engineers listed below.

### Contact Information

Engineer Name	Phone Number
Stefan Lipski	(586) 552-0108
John Hibbeln	(586) 907-4459

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

### Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
-----------------	-------------	------------

1086028*	Engineering Information – Left, Right and/or Both Ground Effects Rockers are Loose and/or Pulling Away From the Body of the Vehicle	0.2 hr
----------	---	--------

\*This is a unique Labor Operation for Bulletin use only.

<b>Version</b>	1
<b>Modified</b>	Released April 01, 2019