

**** SOLUTION ****

Title *Expired - Refer To P20EE Solutions - NOx Conversion Test (Test -- 2549-08-03-03) Interpretation*

Mack Models

Mack Model Cabover , LEU , LR , MRU - TerraPro , Conventional , CHU - Pinnacle, Axle back , CXU - Pinnacle, Axle front , GU - Granite , TD - Titan

Volvo Models

Volvo Model Conventional , VNL , VNM , VNX , VAH , VHD

Emission Standard

Emission Standard US10+OBD13 , US14+OBD13 , US17 , US17+OBD16

Engine family

Engine family Volvo , 11L Engine , 13L Engine , 16L Engine , Mack , MP7 , MP8 , MP10

**** SOLUTION ****

Cause There have been reports of the NOx conversion test being performed when it is not needed causing the results to be interpreted incorrectly.

Solution Please use the NOx conversion test only when one or more of the four fault codes are lighting the lamp (Confirmed DTC).

1. P20EE, P225C and P225E .
2. P2201 (Except OBD2015, Truck MY2016, with engine MSW 22644017 or older).

Please make sure the fault is "confirmed" before performing this operation.

Another reason to run the NOx conversion test is if the vehicle is in SCR inducement with suspected DEF quality concerns (Active P103B, P207F are typical fault codes under this scenario).


NOx conversion test only checks the NOx sensors by comparing against each other. Therefore you will have to use original fault code to determine which sensor to replace if test results are bad.

While running NOx conversion test if any new NOx sensor faults are logged (Egs: P220E-93, P220F-93), make sure to troubleshoot the code (in case of P220E-93 requires NOx1 sensor to be replaced).

Egs: **Truck had MIL ON due to P2201 fault** (NOx1 sensor rationality fault). NOx conversion test showed the following results (Typical Good NOx1 value before shutdown is around 300ppm).

For the case below, we should be replacing NOx1 sensor, not NOx2 sensor.

NOx-in and NOx-out levels vs. Engine speed



Note: "The engine must be cranking is not done within this time"

Result

The test was not executed successfully. Please test again.

Test result

Inlet NOx sensor zero level

Outlet NOx sensor zero level

Recommended actions

Observe the values in the graph for a few minutes. NOx sensors values do not deviate from zero level.

Note: The sensor that failed "Test" is the one that failed.

Sensor replacement is only needed if the NOx level is higher than 10 PPM prior to engine speed increase.

Solution visibility

Dealer distribution

Function(s)/component(s) affected

Function affected: CV electronic control unit, 110 EMS, EECU, MID 128 – EMS, Diagnostic tool, engine, exhaust, EGR, DPF, SCR

Function Group

Function Group: 254 catalytic converter; exhaust emission control equipment, 258 emissions after-treatment

Customer effect

Main customer effect: regeneration, calibration/programming/pairing/missing operation, diagnostics/methodology, efficiency/abnormal behavior, fault code/display

Fluid implicated: AdBlue, air

Lights/Messages on information display: message on display, ----, --/--

Conditions

Vehicle operating mode: when stationary

Frequency of occurrence of problem: always

Administration

Author: ut0031h

Last modified by: RU4469V

Creation date: 08-02-2017 14:02

Date of last update	04-03-2019 20:03
Review date	31-12-2017 00:12
Status	<i>Expired</i>
Average score	1.4285714626312256
Number of scores	7
NA_Reviewer	ut0031h
NA_Author_Group	GTT