



SERVICE BULLETIN

APPLICABILITY: 2018-19MY Legacy and Outback

2018-19MY Crosstrek 2017-19MY Impreza

SUBJECT: New Harman Audio Amplifiers

NUMBER: 15-240-19 **DATE:** 04/18/19

INTRODUCTION:

This bulletin announces availability of new Harman audio unit amplifier units with revised internal logic designed to optimize efficiency while addressing the following customer concerns:

- Loss of audio output after turning the head unit off and back on again in a short amount of time
- Audio volume is temporarily louder than expected after ending a Bluetooth call while using navigation guidance
- No response from the volume control knob.

PRODUCTION CHANGE INFORMATION:

The new amplifiers were incorporated into production as per the table below:

Model	Starting VIN		
Legacy	J3038144		
Outback	J3345456		
Impreza 4-Door	J3623775		
Impreza 5-Door	J3748957		
Crosstrek	K*220847		

PART INFORMATION:

Description	Part Number	Application	
POWER AMPLIFIER ASSEMBLY	86221AL01C	Legacy / Outback	
	86221FL00C	- Impreza	
	86221FL01C		
	86221FL012	Crosstrek	

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

Bulletin Number: 15-240-19; Date: 04/18/19 Page 1 of 2

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

After the customer concern has been confirmed, the service procedure for replacing the power amplifier assembly remains unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Fail Code	Labor Time
HK POWER AMPLIFIER EXCHANGE	B850-815	ZSE-43	0.3
AUDIO SYSTEM TESTING AND DIAGNOSIS	C031-001		0.3

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 15-240-19; Date: 04/18/19 Page 2 of 2