

## **Service Bulletin**

Bulletin No.: 19-NA-090

Date: May, 2019


## **INFORMATION**

Subject: Information on Possible Oil Consumption and/or Leaks, Malfunction Indicator Lamp (MIL) Illuminated - DTC P0300 Set

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	Halisillission.
Buick	Encore	2013	2019				
Chevrolet	Cruze	2011	2016		1.4L (LUJ, LUV)		
	Sonic	2012	2019			1.4L (LO3, LOV)	
	Trax	2013	2019				


Some customers may comment on one or more of the following conditions:  Oil consumption Oil leak MIL illuminated Some technicians may find DTC P0300 (Engine Misfire Detected) set in the Engine Control Module along with a misfire and low compression in one or more cylinders.	Involved Region or Country	North America, Israel
	Condition	Oil consumption Oil leak MIL illuminated Some technicians may find DTC P0300 (Engine Misfire Detected) set in the Engine

Cause



4576900

This condition may be caused by a broken piston ring land.



4576902

**Note:** If the cylinder wall surface has not been compromised, Do Not replace the engine. Only replace all four pistons and rings.

Perform an Engine Compression Test to aid in diagnosing a possible concern of oil consumption/leak from a piston/cylinder. It is recommended that a Cylinder Leakage Test be performed and record the test results to isolate the concern. If excessive leakage to the crankcase has been isolated, the pistons and cylinder walls must be inspected for compromise. Do not replace the engine if marks have been found on the cylinder walls. Only replace the pistons and rings.

4576914

Shown above is an example of a damaged cylinder wall. Scuffing is wide and has removed the crosshatch from the cylinder wall. If marks in the cylinder walls could be felt with the finger nail, engine replacement is recommended.

Version	1
Modified	Released April 30, 2019

Information