



<b>Subject:</b>  <b>CHECK ENGINE LIGHT ON WITH DTC P061B, SURGING ON ACCELERATION, TRANSMISSION WON'T SHIFT PAST 4TH GEAR, VARIOUS U CODES SET</b>	<b>Service Alert No.:</b> SA-011/19
	<b>Last Issued:</b> 05/13/2019

## BULLETIN NOTES

This Service Alert supersedes the previously issued Service Alert(s) listed below: The changes are noted in Red.

Previous Service Alert(s):	Date(s) Issued:
SA-011/19	02/02/19

## APPLICABLE MODEL(S)/VINS

2018-2019 CX-5

## DESCRIPTION

Some vehicles may display some (or all) of the following symptoms:

- Check engine light on wit DTC P061B
- Surging on acceleration
- Transmission will not shift past 4th gear
- Various U codes (U0401 ABS, U0401, U0415 FSC, U0301, U0316 SBS/MRCC, U0442 TCM) may be set

Customers having any of these concerns should have their vehicle repaired using the following repair procedure.

## REPAIR PROCEDURE


1. Verify the customer concern.
2. Before beginning normal diagnosis, inspect the air cleaner assembly. The three (3) attaching tabs at the lower rear area of the air cleaner assembly may not be properly attached. This could accidentally occur during an air filter inspection or replacement.

### Inspection:

1. Open the hood.
2. Grasp the air cleaner assembly by hand and gently pull it toward the front of the vehicle.
  - If the air cleaner assembly moves, inspect the three (3) tabs at the lower rear area of the air cleaner assembly. Ensure that all three (3) tabs are properly attached to the lower air cleaner assembly.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

- If the air cleaner assembly is properly attached, perform normal diagnosis according to the instructions on MGSS online.



3. Verify the repair.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.