

## BR213, 217, 222 [E63/S63] Check Engine Light on with Misfire DTC's

---

Topic number	LI07.61-P-067717
Version	8
Function group	07.61 ME fuel injection/ ignition system
Date	04-10-2019
Validity	BR213 E63 Models BR222 S63 Models BR217 S63 Models
Reason for change	
Reason for block	

---

### Complaint:

Check engine light illuminated.

Engine may be running rough.

Possible fault codes:

P030022 - Combustion misfiring was detected

P030185 - Combustion misfiring of cylinder 1 was detected.

P030285 - Combustion misfiring of cylinder 2 was detected.

P030385 - Combustion misfiring of cylinder 3 was detected.

P030485 - Combustion misfiring of cylinder 4 was detected.

P030585 - Combustion misfiring of cylinder 5 was detected.

P030685 - Combustion misfiring of cylinder 6 was detected.

P030785 - Combustion misfiring of cylinder 7 was detected.

P030885 - Combustion misfiring of cylinder 8 was detected.

### Cause:

Misfire detection in ME software

Attachments	
File	Description
M177LS2 Intake Manifold Leak Area.jpg	M177LS2 Intake Manifold Leak Area

### Remedy:

- Update ME, VGS, and PTCU software using FSF provided by MBUSA
  - Create a PTSS case and an FSF will be provided with instructions by frontline or your FTS
  - Update the aforementioned control units and re-evaluate the vehicle
  - If the complaint is no longer present release the car.

# XENTRY TIPS

---

If the software updates DO NOT remedy the complaint then proceed with next steps:

- 1.) Perform the Following: Smoke test intake/exhaust and check for leaks.
  1. Working each bank one at a time; remove the upstream O2 sensor and install the smoke tip.
  2. Seal around the tip to ensure there are no leaks.
  3. Seal the exhaust tip outlet to the O2 sensor bung.
  4. Turn the smoke machine on at the maximum possible pressure.
  5. Look for leaks in the exhaust.
  6. Using very soapy water (it should create suds by itself by spraying) saturate all connections.
    - Look for signs of bubbles.
    - Move and stress the components.
    - Perform the check with engine cold and after a 5 minute run time (lukewarm).
  7. Working each bank one at a time, install the smoke machine tip into the intake air temperature sensor port.
  8. Remove the oil fill cap.
  9. Turn the pressure up on the smoke machine to maximum and fill the engine with smoke until it begins to come out of the oil fill port.
  10. Reinstall the oil fill cap.
  11. Look for leaks.
  12. Using very soapy water (it should create suds by itself by spraying) saturate all connections.
    - Look for signs of bubbles.
    - Perform the check with engine cold and after a 5 minute run time (lukewarm)
  13. If leaks are found, open a PTSS case and perform the following:
    - Repair the leaks as necessary.
    - Clear the mixture adaptations, clear the fault codes, and perform 3 AMG Engine Adaptation Drives (per the AMG User's Guide).
    - Pull the new injector performance data.
    - Compare the new injector performance data to the initial injection performance data pulled when the car first arrived.
      - The ORA and FRA values should have changed.
      - If the ORA/FRA values have not changed; stop and ask for assistance in the PTSS case.
    - Then perform another 2 AMG Engine Adaptation Drives and pull the injector performance data again.
    - Upload all three injector performance data printouts to the PTSS case.
- 2.) Check driver's side intake manifold for cracks near the rear (see attachments) of the engine.
  1. If damage is found, order a new manifold for the driver's side bank from EPC and OPEN PTSS case with pictures of damage.
  2. Include the following:
    - Production stamp on the damaged manifold (looks like a pair of clocks)
    - Production sticker
  3. If no damage is found, or repair does not remedy complaint proceed to step (3).
- 3.) Inspect ignition coils and verify they are PN: A 177 906 95 00.
  - Replace as necessary.
  - If all coils are PN A 177 906 95 00 swap the coil(s) of the misfiring cylinder(s) with those of cylinder(s) that are not misfiring and road test the vehicle.
    - If the misfires move with the coils, replace the coils and the spark plugs on original misfiring cylinders.
    - If the misfires do not move with coils or do not immediately reappear proceed to step 4.
- 4.) Measure the following grounds. If any reading is above 0.5 ohm, check grounding locations (per attachments).
  - ME Connector F, Pin 1 to ground
  - ME Connector F, Pin 2 to ground
  - ME Connector F, Pin 4 to ground

# XENTRY TIPS

---

- ME Connector M, Pin 6 to ground
- ALL Coils, Pin 1 to ground
- Rework grounding locations by removing and cleaning the chassis ground point(s) of any paint or debris.
- If rework/replacement does not remedy complaint, proceed to step 5.

5.) Perform a Xentry guided high pressure fuel test from cold start and obtain the injector performance data, and initial quick test with fault freeze.

- If the test fails for either bank, replace the high pressure fuel pump for that bank.
- If the test passes for both banks, road test the car with ECO start/stop disabled and allow the vehicle to achieve operating temperature.
  - Shut the vehicle down and observe the fuel pressures on the left and right banks at t=0, t=30 minutes, t=60 minutes, and t>120 minutes.
    - If at any time the fuel pressure drops below the minimum value and/or a large differential exists between the left and right banks, boroscope the cylinders on the bank with low fuel pressure and determine if one or more of the injectors is leaking.
      - If the fuel pressure remains within acceptable limits proceed to step (6).
    - If one or more of the injectors is leaking, open a PTSS case and upload pictures of the failed injector(s) taken with the boroscope as well as the information collected via Xentry thus far.
      - Replace the failed injector(s) and all the injector seals.
      - Update the IMA coding for the new injectors in their respective cylinders via Xentry.
      - Perform an AMG engine adaptation drive (at least 50 miles total).
      - Upload the new injector performance data and quick test to the case.
      - Road test the vehicle. If the complaint is no longer present the PTSS case can be closed and the vehicle released.

6.) Open PTSS Case if Above do not Remedy the Complaint

INCLUDE IN THE CASE:

- 1) All Data from step (5)
- 2) MED1775 Control Unit Log
- 3) Software update check for ME and Transmission control units
- 5) Engine Performance Data
- 6) Injector Performance Data
- 7) Line Graph Version of the Fault Counter from Cold Start
- 8) PICO Compression Test of ALL Cylinders

Attachments	
File	Description
Ground points LS2_BR213_englx.pdf	M177LS2 BR213 Ground Check
Ground Points LS2_BR222 (002).pdf	M177LS2 BR222 Ground Check
Fault Counter.pdf	Fault Counter Instructions
Injection Performance Data.pdf	Injector Performance Data Interpretation

Symptoms
Power generation / Engine management / Engine running / Runs rough/shakes

# XENTRY TIPS

---

Power generation / Engine management / Indicator lamp / Engine diagnosis / lit

## Control unit/fault code

Control unit	Fault code	Fault text
N3/10 - Motor electronics 'MED1775' for combustion engine 'M177' (ME)	-	-