

# Service Information

**Offboard Diagnostic Information System Service (ODIS Service)**

**Number: VOS-19-11**

**Subject: Diagnostic Software - Version Update, Enhancements and Fixes**

**Date: May 23, 2019**

**Supersedes VOS-19-09 due to new diagnostic content version.**

The following ODIS Service software versions are available for download.

Current ODIS Service Software Versions	
Application: <b>V5.1.3</b>	Diagnostic Content: <b>V2.39.1</b>

## **Key Fixes/Enhancements for Diagnostic Content: V2.39.1:**

### **1. A3 - Passat/New Midsize Sedan 2011-2017, CPRA 1.8l Simos / 125 kW.**

P001100: A Camshaft Position (Bank1) Timing over-advanced or System Performance test plan J623\_X\_1\_0918\_11\_X\_ENW\_Verstellung\_pruefen\_00011 malfunction.

Inlet camshaft adjustment test fails and continuously cancels after "Repeat test" is selected.

### **2. CA – Atlas 2018-2019**

-0036- Driver's Side Seat Adjustment - B135354: Seat angle adjustment motor No basic setting and B201000: No basic setting test J810\_X\_1\_0614\_11\_Grundeinstellung\_00000 could not be completed successfully.

### **3. BW – Tiguan 2018-2019**

Basic setting faults B201000: No basic setting and other related basic setting faults are still active and static in J810 - control module for the driver seat adjustment after performing the basic setting function J810\_X\_1\_0614\_11\_Grundeinstellung\_00000.

### **4. A3 – Passat/New Midsize Sedan 2011-2019, DDSA 2.0l Simos/130 kW**

ECM DTCs P0172 - Fuel Trim Bank 1, System too Rich and P2178 - System too rich off idle, Bank 1 test plan SYS\_X\_1\_0616\_X\_X\_GMS\_FSB\_00000 malfunction. Test ends with the following error message:

- Program malfunctionSFB01. During testing, implausible data has been determined.  
Send feedback to support.

### **5. 7P – Touareg 2010 – 2017, CNRB 3.0L TDI-CR/ 176kW**

# Service Information

---

ECM DTC P03A500: cylinder 2 pressure too high test

GXXX\_7P\_23\_CATA\_1\_0610\_11\_Brennraumdruckgeber\_00011 fails due to control module communication.

- The value Cpp phi Pos MC 5 for the request parameter Record Data Identifier could not be entered.

## 6. 5C – Beetle 2012 – 2018, DDSA 2.0l Simos/130 kW.

U110300: Production mode active is static in the ECM, but there is no test plan created for the fault code.

## 7. 3H - Arteon 2018-2019

VIN is not automatically read during vehicle identification and diagnostic protocol sending to GFF Paperless, but entered manually.

## 8. 7P – Touareg 2010-2017, CGRA 3.6 L FSI / 206kW

P229400: Fuel Pressure Regulator "B" Control Circuit/Open N276\_7P\_20CGRA\_1\_0710\_11\_00011 states incorrectly that the actual fuel pressure (measured by the Fuel Pressure Sensor -G247) was higher than the specified value.

- Actual fuel pressure: 5.8bar Fuel pressure; specified value: 69.8bar.

## 9. CA – Atlas 2018-2019

00CA - Power Sunroof Control Module basic setting J245\_3G\_1\_0914\_11\_Grundeinstellung\_00000 could not be performed successfully.

## 10. 16 – Jetta 2011 – 2018, CNLA 1.4l TFSI Hybrid / 110kW

Test SYS34\_1K\_\_DQ\_1\_0607\_11\_Gangsteller\_Neutral\_00011 to move the gear selector to -neutral- position will not release the 6R solenoid correctly and makes it difficult to remove the mechatronic.

## 11. 16 – Jetta 2011 – 2018, CNLA 1.4l TFSI Hybrid / 110kW

J623- erase adaptation values J623\_X\_1\_0115\_11\_X\_X\_MSG\_LW\_loeschen\_00011 aborts due to no answer from the engine control module.

- Reason for aborting: str\_Quickstart = Response status 0 Negative Response.

## 12. 16 – Jetta 2011 – 2018, CJAA 2.0 L TDI CR / 103 kW

The connector at the -J338- Throttle valve control module is a 4 pin connector but test J338\_5K\_23CJAA\_1\_0709\_11\_00011 says to use test adapter 5 Pin Model VAS 5262.

The correct test adapter cable is 4 Pin Model VAS5258A

## 13. General translation errors